



Standard Practice for Fractography and Characterization of Fracture Origins in Advanced Ceramics¹

This standard is issued under the fixed designation C 1322; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ϵ) indicates an editorial change since the last revision or reapproval.

1. Scope*

1.1 The objective of this practice is to provide an efficient and consistent methodology to locate and characterize fracture origins in advanced ceramics. It is applicable to advanced ceramics which are brittle; that is, the material adheres to Hooke's Law up to fracture. In such materials, fracture commences from a single location which is termed the fracture origin. The fracture origin in brittle ceramics normally consists of some irregularity or singularity in the material which acts as a stress concentrator. In the parlance of the engineer or scientist, these irregularities are termed flaws or defects. The latter should not be construed to mean that the material has been prepared improperly or is somehow faulty.

1.2 Although this practice is primarily intended for laboratory test piece analysis, the general concepts and procedures may be applied to component failure analyses as well. In many cases, component failure analysis may be aided by cutting laboratory test pieces out of the component. Information gleaned from testing the laboratory pieces (for example, flaw types, general fracture features, fracture mirror constants) may then aid interpretation of component fractures. For more information on component fracture analysis, see Ref (1).²

1.3 This practice supersedes Military Handbook 790.

1.4 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.*

2. Referenced Documents

2.1 ASTM Standards:³

C 162 Terminology of Glass and Glass Products

C 242 Terminology of Ceramic Whitewares and Related Products

C 1036 Specification for Flat Glass

C 1145 Terminology of Advanced Ceramics

C 1161 Test Method for Flexural Strength of Advanced Ceramics at Ambient Temperature

C 1211 Test Method for Flexural Strength of Advanced Ceramics at Elevated Temperatures

C 1239 Practice for Reporting Uniaxial Strength Data and Estimating Weibull Distribution Parameters for Advanced Ceramics

C 1256 Practice for Interpreting Glass Fracture Surface Features

F 109 Terminology Relating to Surface Imperfections on Ceramics

2.2 Military Standard:

Military Handbook 790, Fractography and Characterization of Fracture Origins in Advanced Structural Ceramics, 1992⁴

3. Terminology

3.1 *General*—The following terms are given as a basis for identifying fracture origins that are common to advanced ceramics. It should be recognized that origins can manifest themselves differently in various materials. The photographs in Appendix X1 show examples of the origins defined in 3.11 and 3.20. Terms that are contained in other ASTM standards are noted at the end of the each definition.

3.2 *advanced ceramic, n*—a highly engineered, high-performance, predominately nonmetallic, inorganic, ceramic material having specific functional attributes. **C 1145**

3.3 *brittle fracture, n*—fracture that takes place with little or no preceding plastic deformation.

3.4 *flaw, n*—a structural discontinuity in an advanced ceramic body that acts as a highly localized stress raiser.

NOTE 1—The presence of such discontinuities does not necessarily imply that the ceramic has been prepared improperly or is faulty.

3.5 *fractography, n*—means and methods for characterizing fractured specimens or components. **C 1145**

¹ This practice is under the jurisdiction of ASTM Committee C28 on Advanced Ceramics and is the direct responsibility of Subcommittee C28.02 on Reliability. Current edition approved December 10, 2002. Published June 2003. Originally published as C 1322 – 96. Last previous edition C 1322 – 02a.

² The boldface numbers in parentheses refer to the list of references at the end of this standard.

³ *Annual Book of ASTM Standards*, Vol 15.02.

⁴ Available from Army Research Laboratory-Materials Directorate, Aberdeen Proving Ground, MD 21005.

*A Summary of Changes section appears at the end of this standard.

3.6 *fracture origin, n*—the source from which brittle fracture commences. **C 1145**

3.7 *grain boundary, n (GB)*—as used in fractography, a volume-distributed flaw that is a boundary facet between two or more grains.

NOTE 2—This flaw is most apt to be strength limiting in course-grained ceramics.

3.8 *hackle, n*—as used in fractography, a line or lines on the crack surface running in the local direction of cracking, separating parallel but noncoplanar portions of the crack surface.

3.9 *mirror, n*—as used in fractography of brittle materials, a relatively smooth region in the immediate vicinity of and surrounding the fracture origin.

3.10 *mist, n*—as used in fractography of brittle materials, markings on the surface of an accelerating crack close to its effective terminal velocity, observable first as a misty appearance and with increasing velocity reveals a fibrous texture, elongated in the direction of crack propagation.

3.11 *Inherently Volume-Distributed Origins:*

3.12 *agglomerate, n, (A)*—as used in fractography, a volume-distributed flaw that is a cluster of grains, particles, platelets, or whiskers, or a combination thereof, present in a larger solid mass. **C 1145**

3.13 *compositional inhomogeneity, n, (CI)*—as used in fractography, a volume-distributed flaw that is a microstructural irregularity related to the nonuniform distribution of an additive, a different crystalline or glass phase or in a multiphase material, the nonuniform distribution of a second phase. **C 1145**

3.14 *crack, n, (CK)*—as used in fractography, a volume-distributed flaw that is a plane of fracture without complete separation. **C 1145**

3.15 *inclusion, n, (I)*—as used in fractography, a volume-distributed flaw that is a foreign body from other than the normal composition of the bulk advanced ceramic. **C 1145**

3.16 *large grain(s), n, (LG)*—as used in fractography, a volume-distributed flaw that is a single (or cluster of) grain(s) having a size significantly greater than that encompassed by the normal grain size distribution. **C 1145**

3.17 *pore, n, (P)*—as used in fractography, a volume-distributed flaw that is a discrete cavity or void in a solid material. **C 1145**

3.18 *porous region, n, (PR)*—as used in fractography, a volume-distributed flaw that is a 3-dimensional zone of porosity or microporosity. **C 1145**

3.19 *porous seam, n, (PS)*—as used in fractography, a volume-distributed flaw that is a 2-dimensional area of porosity or microporosity. **C 1145**

3.20 *Inherently Surface-Distributed Origins:*

3.21 *handling damage, n, (HD)*—as used in fractography, scratches, chips, cracks, etc., due to the handling of the specimen/component. **C 1145**

3.22 *machining damage, n, (MD)*—as used in fractography, a surface-distributed flaw that is a microcrack(s), chip(s), striation(s), or scratch(es), or a combination of these, created during the machining process.

NOTE 3—Machining may result in the formation of surface or subsurface damage, or both.

3.23 *pit, n, (PT)*—as used in fractography, a cavity created on the specimen/component surface during the reaction/interaction between the material and the environment, for example, corrosion or oxidation. **C 1145**

3.24 *surface void, n, (SV)*—as used in fractography, a cavity created at the surface/exterior as a consequence of the reaction/interaction between the material and the processing environment, for example, surface reaction layer or bubble that is trapped during processing.

3.25 *Miscellaneous Origins:*

3.26 *unidentified origin, n, (?)*—as used in this practice, an uncertain or undetermined fracture origin.

3.27 Other terms or fracture origin types may be devised by the user if those listed in 3.11 and 3.20 are inadequate. In such instances the user shall explicitly define the nature of the fracture origin (flaw) and whether it is inherently volume- or surface-distributed. Additional terms for surface imperfections can be found in Terminology F 109 and supplementary fracture origin types for ceramics and glasses may be found in *The Ceramic Glossary*⁵ and Terminologies C 162 and C 242 and in a Specification for Flat Glass C 1036. Examples of additional terms are hard agglomerate, collapsed agglomerate, poorly bonded region, glassy inclusion, chip, or closed chip.

3.28 The word “surface” may have multiple meanings. In the definitions above, it refers to the intrinsic spatial distribution of flaws. The word “surface” also may refer to the exterior of a test specimen cut from a bulk ceramic or component, or alternatively, the original surface of the component in the as-fired state. It is recommended that the terms original-surface or as-processed surface be used if appropriate.

4. Summary of Practice

4.1 Prior to testing mark the specimen or component orientation and location to aid in reconstruction of the specimen/component fragments. Marker lines made with a pencil or felt tip marker may suffice.

4.2 Whenever possible, test the specimen(s)/component(s) to failure in a fashion that preserves the primary fracture surface(s) and all associated fragments for further fractographic analysis.

4.3 Carefully handle and store the specimen(s)/component(s) to minimize additional damage or contamination of the fracture surface(s), or both.

4.4 Visually inspect the fractured specimen(s)/component(s) (1 to 10×) in order to determine crack branching patterns, any evidence of abnormal failure patterns (indicative of testing misalignments), the primary fracture surfaces, the location of the mirror and, if possible, the fracture origin. Specimen/component reconstruction may be helpful in this step. Label the pieces with a letter or numerical code and photograph the assembly if appropriate.

4.5 Use an optical microscope (10 to 200×) to examine both mating halves of the primary fracture surface in order to locate and, if possible, characterize the origin. Repeat the

⁵ The American Ceramic Society, Westerville, OH 1984.

examination of pieces as required. If the fracture origin cannot be characterized, then conduct the optical examination with the purpose of expediting subsequent examination with the scanning electron microscope (SEM).

4.6 Inspect the external surfaces of the specimen(s)/component(s) near the origin for evidence of handling or machining damage or any interactions that may have occurred between these surfaces and the environment.

4.7 Clean and prepare the specimen(s)/component(s) for SEM examination, if necessary.

4.8 Carry out SEM examination (10 to 2000X) of both mating halves of the primary fracture surface.

4.9 Characterize the strength-limiting origin by its identity, location, and size. When appropriate, use the chemical analysis capability of the SEM to help characterize the origin.

4.10 If necessary, repeat 4.6 using the SEM.

4.11 Keep appropriate records, digital images, and photographs at each step in order to characterize the origin, show its location and the general features of the fractured specimen/component, as well as for future reference.

4.12 Compare the measured origin size to that estimated by fracture mechanics. If these sizes are not in general agreement then an explanation shall be given to account for the discrepancy.

4.13 For a new material, or a new set of processing or exposure conditions, it is highly recommended that a representative polished section of the microstructure be photographed to show the normal microstructural features such as grain size and porosity.


5. Significance and Use

5.1 This practice is suitable for monolithic and some composite ceramics, for example, particulate- and whisker-reinforced and continuous-grain-boundary phase ceramics. (Long- or continuous-fiber reinforced ceramics are excluded.) For some materials, the location and identification of fracture origins may not be possible due to the specific microstructure.

5.2 This practice is principally oriented towards characterization of fracture origins in specimens loaded in so-called fast fracture testing, but the approach can be extended to include other modes of loading as well.

5.3 The procedures described within are primarily applicable to mechanical test specimens, although the same procedures may be relevant to component failure analyses as well. It is customary practice to test a number of specimens (constituting a sample) to permit statistical analysis of the variability of the material’s strength. It is usually not difficult to test the specimens in a manner that will facilitate subsequent fractographic analysis. This may not be the case with component failure analyses. Component failure analysis is sometimes aided by cutting test pieces from the component and fracturing the test pieces. Fracture markings and fracture origins from the latter may aid component interpretation.

5.4 Optimum fractographic analysis requires examination of as many similar specimens or components as possible. This will enhance the chances of successful interpretations. Examination of only one or a few specimens can be misleading. Of course, in some instances the fractographer may have access to only one or a few fractured specimens or components.



NOTE—Keep appropriate records, digital images, and photographs at each step to assist in the origin characterization and for future reference.

FIG. 1 Simplified Schematic Diagram of the Fractographic Analysis Procedure

5.5 Successful and complete fractography also requires careful consideration of all ancillary information that may be available, such as microstructural characteristics, material fabrication, properties and service histories, component or specimen machining, or preparation techniques.

5.6 Fractographic inspection and analysis can be a time-consuming process. Experience will in general enhance the

chances of correct interpretation and characterization, but will not obviate the need for time and patience. Repeat examinations are often fruitful. For example, a particular origin type or key feature may be overlooked in the first few test pieces of a sample set. As the fractographer gains experience by looking at multiple examples, he or she may begin to appreciate some key feature that was initially overlooked.

5.7 This practice is applicable to quality control, materials research and development, and design. It will also serve as a bridge between mechanical testing standards and statistical analysis practices to permit comprehensive interpretation of data for design. An important feature of this practice is the adoption of a consistent manner of characterizing fracture origins, including origin nomenclature. This will further enable the construction of efficient computer databases.

5.8 The irregularities which act as fracture origins in advanced ceramics can develop during or after fabrication of the material. Large irregularities (relative to the average size of the microstructural features) such as pores, agglomerates, and inclusions are typically introduced during processing and can (in one sense) be considered intrinsic to the manufacturing process. Other origins can be introduced after processing as a result of machining, handling, impact, wear, oxidation, and corrosion. These can be considered extrinsic origins. However, machining damage may be considered intrinsic to the manufacturing procedure to the extent that machining is a normal step of producing a finished specimen or component.

5.9 Regardless of how origins develop they are either inherently volume-distributed throughout the bulk of the ceramic material (for example, agglomerates, large grains, or pores) or inherently surface-distributed on the ceramic material (for example, handling damage, pits from oxidation, or corrosion). The distinction is a consequence of how the specimen or component is prepared. For example, inclusions may be scattered throughout the bulk ceramic material (inherently volume-distributed), but when a particular specimen is cut from the bulk ceramic material the strength-limiting inclusion could be located at the specimen surface. Thus a volume-distributed origin in a ceramic material can be in any specimen, volume-located, surface-located, near surface-located, or edge-located.

5.10 As fabricators improve materials by careful process control, thus eliminating undesirable microstructural features, advanced ceramics will become strength-limited by origins that come from the large-sized end of the distribution of the normal microstructural features. Such origins can be considered mainstream microstructural features. In other instances, regions of slightly different microstructure (locally higher microporosity) or microcracks between grains (possibly introduced by thermoelastic strains) may act as failure origins. These origins will blend in well with the background microstructure and will be extremely difficult or impossible to discern even with careful scanning electron microscopy. This practice can still be used to analyze such failure origins, but specific origin definitions may need to be devised.

NOTE 4—See appendix reference was ap00044 for examples.

6. Apparatus

6.1 *General*—Examples of the equipment described in 6.2 through 6.6 are illustrated in Appendix X4.

6.2 *Binocular Stereomicroscope*, with adjustable magnification between 10 to 200× and directional light source (see Fig. X4.1). A camera or video monitor system used with this microscope is a useful option (see Fig. X4.2).

6.3 *Cleaning and Preparation Equipment*, such as an ultrasonic bath and a diamond cut-off wheel.

6.4 *Scanning Electron Microscope (SEM)*, with energy or wavelength dispersive spectroscopy (see Fig. X4.3).

6.5 *Peripheral Equipment*, such as hand magnifying lens; 5×, 7×, or 10× inspection loupe; tweezers; grips; felt tip pens; and compressed air, as shown in Fig. X4.4.

6.6 *Macrophotography Camera Stand* (see Fig. X4.5), if a camera system is not available on the stereomicroscope.

6.7 *Computer and Appropriate Software (Optional)*, for retention and filing of digital images. JPEG and TIFF file formats are the most common for fractographic images.

7. Detailed Procedures and Characterization

7.1 Procedure:

7.1.1 *General*—Location, identification, and characterization of fracture origins in advanced ceramics can sometimes be accomplished using simple optical microscopy techniques though it more often requires scanning electron microscopy (SEM). It may not be feasible, practical, or even necessary to examine all fracture surfaces with the SEM. The extent of fractographic analysis required will depend upon the purpose of the analysis and the fractographic conduciveness of the material.

7.1.1.1 The nature of the fractographic analysis will depend on whether the results will be used for quality control, materials research and development, or design. Table 1 gives suggested sampling guidelines for medium-to-high strength advanced ceramics.

7.1.1.2 The fractographic analysis will also depend on the conduciveness of the material to this analysis. Some ceramics are easy to analyze; fracture origins are readily visible with an optical microscope and the SEM is not needed. Alternatively, origins may be too small to discern with an optical microscope, difficult to differentiate from the normal microstructure, or too difficult to see in some translucent materials, thus, the SEM examination is necessary. Coarse-grained or porous materials may have no fractographic markings that permit origin identification, and optical and SEM microscopy will prove useless.

7.1.2 An origin type may not reveal itself clearly in some specimens and may only be detected after a number of examples are viewed and a pattern begins to emerge. It is often necessary to reexamine many of the specimens and reevaluate the initial appraisal. Fractographic interpretations based on only one or a few specimens can be very misleading.

NOTE 5—The examination of all specimens shall include the examination of both mating halves of the primary fracture surface irrespective of the purpose of the fractographic analysis.

7.1.3 To maximize the amount of information obtained from a fractographic exercise, care shall be taken in all steps starting with the initial testing of the specimen or component.

TABLE 1 Suggested Sampling Guidelines

Level	1 to 10× Visual	10 to 200× Optical	10 to 2000× SEM
Level 1 Quality control	Specimens that fail to meet minimum strength requirements	Specimens that fail to meet minimum strength requirements	Optional
Level 2 Quality control Materials development	All specimens	All specimens, if possible, always both fracture halves; see Note 5	Representative specimens, for example: —2 of each origin type —the 5 lowest strength specimens —at least 2 optically unidentifiable origins, if present
Level 3 Materials development Design	All specimens	All specimens, if possible, always both fracture halves; see Note 5	All specimens, or as many specimens as necessary such that combined optical and SEM characterize 90 % (100 % for design) of all identifiable origins

7.1.4 Specimens that fail during machining, handling, or without measurement of a failure stress, should be examined, when feasible, to determine the fracture origins. The fact that these types of fracture occurred should be noted and reported.

7.1.5 *Mechanical Testing*—A few simple precautions should be taken prior to breaking the specimen. The test site should be kept clean to minimize pickup of contaminants. Markings of some sort should be placed on the specimen to maintain a point of reference and to aid in the reconstruction of the specimen. The markings shall not damage the specimen or lead to contamination of the fracture surfaces. A fine pencil or felt tip marker line is often sufficient to mark the inner gage length in a flexural strength specimen. The tension and compression sides of the specimen may also be marked. A circular direct tension strength specimen may be marked with a zero-degree reference. Testing that allows the broken fragments of the specimen to hurtle about shall be avoided. Incidental impact damage to the fracture surfaces can destroy the origin, alter its appearance, or cause secondary fractures. A compliant material that covers the hard surfaces of the fixture or prevents pieces from flying about, or both, is sufficient to minimize this damage. All fragments from the broken specimen shall be retained for reconstruction, unless it can be positively established that some pieces are incidental or trivial. In some cases, tape may be applied to a test piece prior to testing in order to hold fragments together after fracture. Tapes shall not be applied to tensile loaded specimen surfaces, nor shall they interfere with the application of forces or loads on the test piece. For example, portions of the back (compression) surface of a biaxial disk specimen for ring-on-ring testing may be taped, but the annular region where the inner loading ring contacts the test piece should be left untaped.

7.1.6 *Handling and Storage*—Broken specimens shall be handled and stored so as to minimize the possibility of damage or contamination of the fracture surfaces, or both. Avoid handling the specimen, especially the fracture surface, with your hands. Body oils and skin fragments can easily change or obscure the character of the fracture surface. During reconstruction of the specimen, minimize rubbing the fragments together since this may abrade or chip the fracture surfaces, and damage the fracture surface. Avoid picking or even touching the fracture surface with sharp instruments such as tweezers as this may alter or contaminate the fracture surface.

The specimen shall be stored in a clean and orderly fashion as much time can be lost trying to sort out mixed-up specimens. Store the specimen and fragments in containers that will minimize additional damage or contamination.

NOTE 6—The laboratory environment contains a myriad of materials such as clays, waxes, adhesives, and resins that should be avoided wherever possible. Many of these materials, once they are affixed to the specimen, are very tenacious and often impossible to remove.

7.1.7 *Visual Inspection and Specimen or Component Reconstruction (1 to 10×)*—Visually examine the fragmented specimen/component pieces in order to find the primary fracture surfaces, the general region of the fracture origin, and if possible the fracture mirror. Hand magnifiers or inspection loupes can be helpful. Reconstruct the specimen if necessary, but take care to avoid damaging the fracture surfaces of pieces that have the prospective fracture origin. Reconstruction is valuable in observing the crack(s) and crack branching patterns which, in turn, helps determine the primary fracture surfaces and can help assess the stress state if it is not known. Special emphasis should be on determining whether the fracture pattern indicates misalignments or breakages at test grips (in tension), at stress concentrators (neck region in tension), or load application points (in flexure and disk tests).

7.1.7.1 Crack patterns can range from very simple to quite complex depending upon the specimen or component geometry and the stress states in the body. Multiple fractures are common to high-strength ceramics that store large amounts of elastic energy during testing. Upon failure, this energy is released and reflects from free surfaces back through the body of the material causing additional fractures. Appendix X6 shows many potential fracture patterns in some common test specimens. A hierarchy or sequence of crack propagation can assist in backtracking to the primary fracture surfaces. Crack branching can be used to determine the direction of crack propagation. A traveling macrocrack will typically branch into successively more cracks and will rarely rejoin another crack to form a single crack (see Fig. 1). A crack that intersects another crack at angles close to 90° and stops (does not continue into an adjacent piece) will usually be a secondary crack that can be quickly eliminated since it will not contain the fracture origin. For specimens that do not show macroscopic crack branching, incipient branching in the form of shallow cracks can often be

found along the edge of the main crack on the exterior surface. As with the macroscopic cracks, the angle of these shallow cracks in relation to the main crack indicate the local direction of crack growth. Vicinal illumination or dye penetrants, or both, may be used to make these cracks more easily discernible.

7.1.7.2 Misalignment or deviation from the assumed stress state can be discerned by fracture surfaces that are at an irregular angle (not 90°) to the anticipated maximum principal stress. Branching angles can be helpful in detecting multiaxial stress states. Frequent breakage at test grips (in tension), at stress concentrators (neck region in tension), or load application points (in flexure and disk tests) may indicate misalignment.

7.1.7.3 The detection of the general region of the fracture origin, and the fracture mirror if present, during visual examination depends on the ceramic material being analyzed. Dense, fine-grained, or amorphous ceramics are conducive to fractography and will leave distinct fracture markings (hackle and mirror) which will aid in locating the origin (see Fig. 2). Hackle lines and ridges on the fracture surface are extremely helpful in locating the general vicinity of a fracture origin, even when a fracture mirror is not evident (Fig. 3). They will radiate from, and thus point the way back to, the fracture origin. They are best highlighted by low incident angle lighting which will create useful shadows. Fracture mirrors are telltale features that are typically centered on the strength-limiting origins. If the specimen or component is highly stressed, and the material is fine-grained and dense, a distinct fracture mirror will form as shown in Fig. 2. On the other hand, lower energy fractures and those in coarse-grained or porous ceramics will not leave distinct fracture markings (Fig. 3). Coarse hackle markings or ridges can still be used to determine the vicinity of the fracture origin, especially with oblique lighting.

NOTE 7—Coarse-grained or porous materials may have no fractographic markings that permit origin identification, and optical and SEM will prove useless.

7.1.8 *Optical Microscopy (10 to 200×)*—Examine both mating halves of the primary fracture surface. This is often performed in conjunction with the visual inspection. The purpose of the optical examination is to locate the fracture origin on the primary fracture surfaces (Table 1, Levels 2–3) and attempt to characterize the origin. If characterization is not possible during this step, the optical examination helps to minimize the time spent during the subsequent SEM examination.

7.1.8.1 A stereomicroscope is preferred for examining fracture surfaces due to its excellent depth of field. Viewing will be most effective in the 10 to 200× range since at higher magnifications the depth of field is reduced. A traversing stage coupled with crosshairs or a graduated reticule in the eyepiece is useful for measuring the size or area, or both, of the mirror and, if possible, the origin. Illumination should be provided by a common microscope light source with adjustable intensity and angle of incidence to provide a means of variable lighting. These variations can highlight aspects of the fracture surface that may be hidden if one is restricted to a single view. Low

angle grazing illumination (vicinal) is especially valuable in highlighting ridges, valleys, hackle lines, and other features on the fracture surface.

7.1.8.2 The specimen should be mounted to view the fracture and external surfaces. A holder, such as a simple alligator clip attached to a stand with a flexible arm and having a compliant coating or sheath covering the teeth, provides a sturdy grip (Fig. X4.4) for examination. Viewing both of the mating primary fracture surfaces simultaneously can expedite and improve the quality of the analysis since what might appear to be a pore on one half may show an agglomerate on the other (flexure specimens should be mounted tensile surface-to-tensile surface). Care shall be taken so that extraneous damage is not created.

NOTE 8—DO NOT use clays or waxes for mounting because these materials can contaminate the fracture surface and are very difficult to remove. Surface contaminants such as lint and dust can be removed easily with canned or filtered compressed air.


NOTE 9—Additional illumination techniques and helpful procedures are as listed in X2.1.1.

7.1.8.3 At the lowest magnification, locate the mirror using the hackle on the fracture surface. In high-strength, fine-grained, and dense ceramics the origin will be approximately centered in the fracture mirror as shown in Fig. 2b and Fig. 2c. Hackle lines and ridges will be very helpful since they will radiate outward from the fracture origin and mirror. As discussed in 7.1.7, low energy fractures or fractures in porous or coarse-grained ceramics may not lead to mirror formation, but the same principles of using the hackle lines apply. Twist hackle lines are especially helpful and occur when a crack encounters a principal stress field that is not perpendicular to the original plane of fracture. Twist hackle commences as finely spaced parallel lines which usually merge in the direction of crack propagation, giving rise to the well known river pattern as shown in Fig. 4.

NOTE 10—The merger of twist hackle in the direction of crack propagation is opposite to the tendency of macrocracks to diverge as discussed in 7.1.7.1. These features are usually well defined in glasses and very fine grained, fully dense polycrystalline ceramics. Such twist hackle often occurs on individual grains in coarse-grained polycrystalline ceramics. (See X2.1.1 for a discussion and illustration of these features.)

7.1.8.4 Examine the external surfaces of the specimen or component if the origin is surface- or edge-located. A specimen holder (Fig. X4.4) with a flat or vee groove can be used to hold the entire specimen at a convenient working height to view the external surfaces. This examination can be especially helpful if the origin is not evident on the fracture surface and handling or machining damage is suspected. It is also helpful in ascertaining if any interaction/reaction has occurred between the material and the environment.

7.1.8.5 Characterize the identity, location, and size of the strength-limiting origin in accordance with 7.2. Record observations pertaining to features specific to the lighting, such as color and reflectivity. These records should include, but not be limited to, notes, sketches, and photographs. Although this extra step may seem time-consuming, it often leads to greater efficiency in the long run. These records are extremely useful for publication and minimizing the search time with the SEM.



NOTE 1—

- (A) A schematic of a flaw located at the surface.
- (B) An optical micrograph of a surface-located flaw in a biaxial borosilicate crown glass disc fractured in a biaxial ring-on-ring strength test ($\sigma = 118$ MPa).
- (C) A schematic of a flaw located near the surface.
- (D) An optical micrograph of a near-surface located flaw in a tungsten carbide specimen tested in 4-point flexure ($\sigma = 724$ MPa).
- (E) Schematic of a flaw located near the surface.
- (F) An optical micrograph of a volume-located flaw in a siliconized silicon carbide tension specimen ($\sigma = 350$ MPa).

NOTE 2—The mirror can be centered around a portion of the origin and not the entire origin. In ceramic terminology, smooth is a relative term.


FIG. 2 Fracture Surfaces of Advanced Ceramics That Failed in a Brittle Manner

The latter point can not be underestimated. Novices often lose much time searching for the origin or examining the wrong area with the SEM. The SEM images are quite different from optical images, and a reorientation time is sometimes necessary. Appendix X1 and Appendix X9 may be consulted for examples of fracture origins and typical signs of machining damage origins.

7.1.8.6 Reexamine the specimen fracture surfaces if necessary. This will be important if a new material is being examined

or if a particular origin type becomes clear only after some or all of the specimens have been examined.


7.1.8.7 Photograph the fracture surface, if appropriate (see 7.1.10). A camera directly mounted on the stereo binocular microscope is especially valuable and a great time saver. With built-in zoom ranges from 5 to 1 and beam splitters, it is possible to frame, focus, and shoot quickly and efficiently. Modern built-in video or digital cameras with monitors can be coupled to color printers which give photograph-size hard



NOTE 1—The coarse hackle lines that emanate from the flaw can be used to locate the origin.

NOTE 2—The coarse hackle lines are obvious (arrows) and clearly indicate the location of the origin (a Knoop indentation-induced pre-crack), even though a mirror is NOT readily visible.

FIG. 3 (A) Schematic of a Flaw in Which a Mirror Has Not Formed and (B) an Optical Micrograph of a Fracture Surface of a Sintered Silicon Nitride Flexure Specimen ($\sigma = 227$ MPa)



NOTE 1—The direction of crack propagation is shown by the arrow.

FIG. 4 Schematic of Twist Hackle Lines That Form a “River Pattern”

copies in less than one minute and without the need to deal with film and negatives. In many instances, digital photography eliminates the need for film, permanent hard copies, or prints. Digital images, with appropriate software, can also be stored in a computer and backed up with storage media such as floppy or laser disks. Such optical images can then be retrieved and displayed on a video monitor or on the SEM monitor. This is a very efficient means of coupling the two methods, and enhanced productivity will result. Photomacrography with a

camera with extension bellows or tubes (Fig. X4.5) is also valuable for recording entire components or structures, especially after reassembly. Photomacrography systems are not expensive and have good depth of field and resolution.

NOTE 11—The *Metals Handbook* listed in Appendix X2, has some helpful tips on lighting techniques for photomacrography.

7.1.8.8 For translucent ceramics, it may be useful to illuminate the fracture surface from the side with low incident angle illumination. An opaque card held next to the specimen side can block the light entering the specimen bulk. This will minimize light scattering from inside the specimen. Alternately, it may be useful to coat the fracture surface with evaporated carbon or sputtered gold-palladium prior to optical examination. This will often improve the visibility of some crack propagation patterns, eliminate subsurface reflections, and improve the quality of the photographs taken of the fracture surface. A simple effective expedient is to stain or “paint” the fracture surface with a green felt tip pen. The dye will mask internal reflections and run into valleys and depressions, highlighting and bringing out the texture in fracture surface markings. The dye may be easily removed with acetone or alcohol on a cotton tipped swab. Such dyes may not be advisable if chemical analysis of the origin during subsequent SEM examination is necessary.

NOTE 12—Be careful! Gold or carbon coatings that are too thick can cover or obscure submicron pores and subtle features in very high-strength advanced ceramics. In these instances it is suggested that the SEM examination (7.1.9) be carried out on uncoated specimens at a low voltage prior to this coating. Also, subtle color or contrast variations will be lost or obscured if the specimen is coated.

7.1.8.9 In some applications, replicas of a fracture surface may be used advantageously, especially with large component fracture analysis or with translucent materials wherein internal

reflections obscure the fracture surface. Although extra preparation steps are involved, cellulose acetate, polyvinyl chloride (PVC), or silicon elastomer replicas can record important features, both for optical and SEM examination. Advantages include (1) elimination of obscuring subsurface features which may hinder the optical microscopy of transparent or translucent ceramics; (2) provision of an easily stored record of the fracture surface of a critical specimen; (3) greater accessibility of curved surfaces to high-magnification optical study; or (4) study of unique specimen geometries. Disadvantages include the risk of altering the fracture origin (for example, pull-out of an agglomerate) and loss of color, contrast, or reflectivity discrimination.

7.1.8.10 (j) *Optional Fracture Mirror and Branching Distances*—It is highly recommended that estimates of the fracture mirror size (mist-hackle boundary) be made for some or all of the specimens in the sample set or in the components. The mirror measurements may either be r_i for the inner mirror (mirror-mist boundary), r_o for the outer mirror (the mist-hackle boundary), or both. In addition, the distance, r_b , to the first major crack branching (where the primary crack splits into two or more cracks) may be measured. Uniform guidelines for such measurements currently do not exist, and the fractographer should clearly state in the report what criteria were used and illustrative pictures or sketches shall be prepared. See Appendix X7 for more information.

7.1.9 SEM Examination (10 to 2000 \times)—Examine both mating halves of the primary fracture surfaces of some or all specimens in the SEM. Optical microscopy is not always adequate to characterize fracture origins. This is especially true for strong materials which have very small mirror regions and smaller origins. Nevertheless, optical microscopy is an essential adjunct to SEM examination since telltale color, contrast, or reflectivity features, as well as subtle features such as mist, and Wallner lines, may be completely lost in electron-microscope viewing. Once optical fractography is complete and the origins are characterized as well as possible, a subset of specimens should be prepared for SEM analysis. Determination of the number of specimens which will comprise the subset will depend on the intent of the analysis (see Table 1).

7.1.9.1 Preparation:

7.1.9.2 (a) If necessary the specimens should be cut to a consistent height that allows for ease of installation and movement in the SEM. Wet cutting should be done so as to flush away the specimen and cutting wheel debris. They should be cut as flat as possible to eliminate problems due to excessive tilt, although a slight tilt backwards can be beneficial on flexure specimens (this allows for the simultaneous viewing of the fracture and tensile surfaces). During the cutting process, every possible measure should be taken to prevent damage to the fracture and external surfaces.

7.1.9.3 (b) Cut specimens should be ultrasonically cleaned in water or an alternate fluid to remove any cutting solutions or other contaminants. Specimens should then be rinsed in a quickly evaporating solvent to remove any final residue. Solvents such as acetone or ethanol are recommended for this step. Once cleaned, each specimen should be properly labeled and placed in a separate glass or plastic container to prevent

contamination. All subsequent handling should only be done with tweezers or lint-free gloves and the specimens should not be brought into contact with tapes, clays, waxes, or fibrous materials.

7.1.9.4 (c) Coating of a ceramic is widely used to reduce charging of the surface and enhance resolution and contrast. However, some of the new SEM equipment is capable of operating at low accelerating voltages which minimizes charging. If such equipment is available, and time permits, it is recommended that the fracture surfaces first be viewed without a coating. The use of low accelerating voltages can provide a better view of the surface topography. If a coating is needed it should be carefully applied. Coatings that are too thick or multiple coatings may obscure features and lead to misinterpretation of the origins.

7.1.9.5 (d) A thin coating, typically 5 nm, of carbon or gold-palladium should be applied onto the specimens using a vacuum evaporator or sputter coater. The gold-palladium coating is recommended for imaging purposes since it provides better conductivity. Carbon coatings deposited by evaporation are preferred for X-ray emission analysis because carbon is nearly transparent to X rays. A thermal evaporation method for metal coatings can be used with a specimen tilted relative to the metal source, creating an oblique deposition. This can be used to create shadows that highlight very fine markings on the specimen.

7.1.9.6 (e) Specimens may be mounted for examination either singly or multiply on stubs using conductive paints. Both mating halves of the primary fracture surface of each specimen shall be mounted. Specimens shall be mounted with the cut surface down and care shall be taken to avoid getting conductive paint on the fracture surface or upper portion of the external surfaces. The specimens shall be mounted in a systematic fashion to permit rapid orientation by the observer. For example, flexure bars should be aligned with their tensile surfaces the same way. If a pencil is used to mark the specimen orientation or the approximate location of the origin, exercise care that no traces of the pencil material get on or near the fracture surface. Once mounted, specimens may be sprayed with compressed air to remove any lint or lightly clinging debris.

7.1.9.7 Examination—Begin the examination by orienting the specimen in the monitor while viewing the specimen at the lowest magnification. Locate the fracture mirror at the lowest magnification. It is often useful to use an optical photograph as a guide when trying to locate the fracture mirror. Adjust the contrast and brightness to provide the maximum amount of information. The entire surface should be photographed at a low magnification to provide a frame of reference for later work. Conventional practice is to orient the specimen image in a consistent manner, that is, place the tensile surface of a flexure specimen at the bottom of the photograph.

7.1.9.8 (a) The SEM may be used either in the secondary electron or backscattered electron modes. The former gives a fully illuminated image of the surface topography with better spatial resolution while the latter provides greater height contrast due to its sensitivity to the detector orientation. Features not in direct line with the detector are darker or even

in shadow. Backscattered electrons carry both topographic and compositional data. This is valuable for detecting inhomogeneities and inclusions. The topographic and compositional signals can be separated for further analytical flexibility. If the analyst is unsuccessful in characterizing the origin using the secondary electron mode, then the backscattered electron mode should be tried, or vice versa.

7.1.9.9 (b) Locate, characterize, and photograph the fracture origin. It should be approximately in the middle of the fracture mirror if a mirror exists. Hackle lines which typically radiate from the fracture origin can also be used to find the origin.

7.1.9.10 *Optional*—If the fracture mirrors are too small to measure with the optical microscope, then fracture mirror sizes may be measured from SEM images.

7.1.9.11 (c) Characterize the identity, location, and size of the origin in accordance with 7.2. It may be necessary to acquire an energy- or wavelength-dispersive X-ray analysis of both the origin and the background to determine whether there are any chemical differences.

7.1.9.12 (d) Examine the external surfaces of the specimen or component if the origin is surface located. In some cases, such as when handling or machining damage are suspected, it may be necessary to tilt the specimen slightly in order to view a portion of the external surfaces. Sometimes a 180° rotation can help discern subsurface machining-related cracks.

7.1.9.13 (e) Photograph the fracture origin. This will typically be in the 200 to 1000× range. Use a magnification in which the origin accounts for approximately one third of the frame area. A photograph showing the fracture mirror and some hackle is also very helpful for later reassessment of an origin. In many cases, photographs at varying magnifications are necessary to furnish all the required information regarding the failure of the specimen. It is recommended that, whenever possible, a consistent set of magnifications and orientations be used to permit comparative assessments between specimens. Stereo photographic pairs sometimes can reveal topographical details that are important to origin characterization.

7.1.9.14 (f) Maintain notes and records of the fractographic findings. These may include sketches of the fracture surface, notes on the origin type and appearance, location of photographs taken, magnification and reference numbers of photographs, whether or not X-ray spectra were acquired, and the location used to acquire the spectra. When maintaining notes of acquired X-ray spectra, always include the accelerating voltage, probe current, magnification, dead time, counts and scan time, working distance, and whether the spectra was taken in scan or spot mode.

7.1.9.15 (g) Repeat the steps in the SEM examination (7.1.9.7) for the mating half of the primary fracture surface.

7.1.9.16 (h) Examine the region in the vicinity of the fracture origin to detect any evidence of stable crack extension or slow crack growth (SCG). If an origin is surface located, it may be susceptible to environmentally assisted SCG. If fracture is at elevated temperatures, SCG can occur from surface- or volume-located origins. Intergranular crack features near the origin surrounded by transgranular or mixed transgranular plus intergranular fracture often are suggestive of SCG. However,

intergranular markings may be difficult to distinguish from microporosity in some materials.

7.1.9.17 (i) *Optional*—In polycrystalline ceramics, observe and record the mode of crack propagation (transgranular or intergranular) in the vicinity of the origin and also in the region outside the mirror.

7.1.9.18 (j) *Optional*—If the fracture mirrors are too small to measure with the optical microscope, then fracture mirror sizes may be measured from SEM images.

7.1.10 *Recording Fractographic Observations*—It is recommended that, whenever possible, three photographs be taken of each fracture surface (one set per pair of fracture halves is adequate). A mix of optical and SEM images is satisfactory. As seen in Fig. 5, these should include, but not be limited to:

- (1) A photograph (optical or SEM) of all or most of the entire fracture surface;
- (2) A photograph of the fracture mirror and some surrounding detail; and
- (3) A photograph of the origin.

NOTE 13—This idealized procedure of three photographs per fracture surface is the most comprehensive record keeping practice. It may be impractical or too time-consuming to perform this on every specimen in a sample set. At a minimum, it should be done for several representative specimens. In many instances, a reexamination or reappraisal of an origin is needed, and a single closeup photograph of an apparent origin is inadequate since the photograph may be incomplete or of the wrong feature. In such instances, photographs of the whole fracture surface and mirror region are invaluable.


7.1.11 It is highly recommended that a representative polished section be made and photographed to reveal the normal microstructure of the ceramic and allow an assessment of whether the origins are abnormal or normal microstructural features. The polished section should be thermally or chemically etched if necessary.

7.2 *Origin Characterization:*

7.2.1 *General*—The fracture origin in each specimen/component shall be characterized by the following three attributes: identity, location, and size, as summarized in Table 2. See Fig. 6 and Fig. 7. For example, pore, volume-distributed; near surface; 30 μm. Origins are either inherently volume-distributed throughout the bulk of the material (for example, agglomerates, large grains, or pores) or inherently surface-distributed on the material (for example, handling damage, pits from oxidation, or corrosion). An inherently volume-distributed origin in a ceramic material can, in any single specimen or component, be volume-located, surface-located, near surface-located, or edge-located, as seen in Fig. 8. The variety of locations for a volume-distributed origin is a consequence of the random sampling procedure incurred in preparing specimens or components (for example, machining).

7.2.2 *Origin Characterization—Identity:*

7.2.2.1 Characterize the origin by a phenomenological approach which identifies what the origin is and not how it appears under a particular mode of viewing. Descriptions of the mode of viewing may be used as qualifiers, for example, pores that appear white when viewed optically, but use of only the appearance, white spots, should be avoided. (This approach is chosen since origins appear drastically different in optical versus electron microscopy.)



NOTE 1—(b) shows a sintered reaction bonded silicon nitride rod flexural strength specimen that had an inclusion origin $\sigma = 751$ MPa maximum, 684 MPa at the origin center.

FIG. 5 Schematic (a) and Example (b) of the Three Photographs Suggested for Recording Fractographic Observations

TABLE 2 Origin Characterization Scheme

Identity	Location	Size
Nomenclature and inherent spatial distribution:	Spatial location of an individual origin in a specific specimen:	Estimate of the diameter for equiaxed origins, or
Volume-distributed, or surface-distributed	Volume-located, or surface-located, or near surface-located, or edge-located	Minor and major axes of volume-distributed origins, or depth and width of surface-distributed origins
		See Figs. 6 and 7

7.2.2.2 Use the nomenclature system of Section 3 if possible. The nomenclature is designed to identify the origin by name (for example, pore, inclusion) and is classified based on the inherent spatial distribution as discussed in 5.9 and 7.2.1. It should be recognized that not all origins can be so characterized and that some origins may be specific to a material and its process history (see 3.27).

7.2.2.3 There may be multiple origin types coincident at a fracture origin. When such mixed attribute cases arise, some judgment is required as to which origin is primary or intrinsic. The fractographer shall determine which origin type is primary and use an ampersand (&) between the primary and secondary origin codes for reporting and graphical representation purposes.


(For example, $P^V \& LG^V$ denotes the origin is primarily a volume-distributed pore but with some associated large grains.)

NOTE 14—Origins can sometimes be difficult to characterize if they have mixed attributes. For example, porous regions often have pores associated with them. It is very common for machining damage surface cracks to link up with porosity, or other flaw types, at or just below the surface. If there is any doubt about the origin characterization, a more complete description of the origin type should be contained in the report.

7.2.2.4 In some mixed attribute cases it is impossible to determine which origin type is primary. The fractographer shall then use a back slash (/) between the identity codes in the report and graphical representation, (agglomerate or pore, A^V/P^V) to indicate the identity of the origin could be one or the other.

7.2.2.5 Some high strength ceramics ($\sigma \geq 1000$ MPa) may fracture due to the combined effects of multiple origin types which are centrally located in the fracture mirror. From a fracture mechanics analysis neither origin type is large enough to initiate fracture, but together they are large enough to cause fracture. A plus sign (+) shall be used in the report and graph representation to indicate that these origin types linked together to limit the strength of the ceramic. (For example, $P^V + MD^S$

Fracture Surface



NOTE 1—Origins can be characterized as near-surface (NS) depending upon whether they are within the distances illustrated. The origin size is the diameter for equiaxed origins, and is the length of the minor and major axes of an elongated origin. All measurements dimensions are approximate only.

FIG. 6 Schematic Showing Origins and Their Dimensions Relative to the Specimen Surface

indicates volume-distributed pore combined with machining damage to become the fracture origin.)

7.2.2.6 In some ceramic materials there may be multiple origin populations within the same origin type, (large alumina grains or large zirconia grains in a zirconia-toughened alumina), which limit the strength of the material. In such instances a subscript shall be used to differentiate each population (LG_a^V indicates large alumina grains and LG_z^V indicates large zirconia grains).

7.2.2.7 In instances where the specimen is examined but the origin identity cannot be determined, the origin shall be designated as an unidentifiable origin, as listed in 3.26 and a question mark (?) will be used in the report or graphical representation as shown in Fig. 9.

7.2.2.8 In cases where the identity of the origin can be estimated, but is not certain, a question mark may be appended to the identity code, for example, Pore(?) or P^V?

7.2.2.9 When a specimen has not been examined, it shall be recorded as not examined and a hyphen (-) will be used in the report and graphical representation to denote this.

7.2.3 Origin Characterization—Location:

7.2.3.1 Characterize the location of a specific origin qualitatively in a given specimen/component. The origin shall be characterized as being volume-located (bulk-located), surface-located, near surface-located, or edge-located (if an edge exists), for example, pore (volume-distributed), surface-located.

NOTE 15—The origin location, which specifies *only* the location of the strength-limiting flaw in a given specimen, shall not be used to statistically differentiate origin populations.

7.2.3.2 Origins shall be considered surface-located in a specimen or component if the origin is in direct contact with an external surface. If there are two or more types of external surfaces (for example, a rectangular flexure specimen that has side and tensile surfaces, or a biaxially-loaded disk with a polished tensile and outer rim surfaces), the surfaces shall be


differentiates. Origins which are located at the juncture of two external surfaces (the chamfer or corner of a flexure or tensile specimen) shall be considered edge-located.

7.2.3.3 In some instances, it is useful to specify the origin location if it is near, but not in direct contact with the external tensile surface. This location category shall be termed, near surface (NS)-located. This additional specification of location is important for fracture mechanics evaluation of origins and service-performance issues. For example, some near surface-located origins may be more susceptible to time-dependent crack growth than equivalent volume-located origins. Near surface-located origins may also be likely to link up with surface machining or impact damage or to extend subcritically to the surface prior to catastrophic fracture. In order to be considered near surface-located rather than volume-located, the origin shall be no more than one times the size of the origin diameter or major axis below the tensile surface. The proximity to the tensile surface shall be noted by estimating the perpendicular distance from this surface to the closest point of the origin, see Fig. 6. If the results of the fractographic analysis are to be used for design purposes (Table 1, Level 3) then the fractographer may wish to consult further with the design engineer regarding the near-surface classification. Alternative criteria for the NS classification may apply in some instances. This criteria, with supporting reasoning, shall be included in the report section.

7.2.4 Origin Characterization—Size:

7.2.4.1 Characterize the origin size. The size need not be measured precisely as this characterization is intended to describe the general nature of the origins (the 20- μ m pore versus the 1- μ m porosity). A fully quantitative size characterization is permitted (but not required) by this practice.

NOTE 16—Precise origin measurements are usually not helpful since the origins' true size may not be revealed on the fracture surface, and exact fracture mechanics analyses of most origins are not possible due to their complex shape. An important exception to this is machining damage



NOTE 1— Y_{max} is shown for each example. The Y at the other points of the crack periphery is shown (in parentheses) for comparison in a few examples.
 NOTE 2—See Note 19 for the applicability of these factors to flexural loadings.

FIG. 7 Stress Intensity Factors (Y) for Penny-Shaped (Circular) and Elliptical Cracks or Semicircular and Semielliptical Surface Cracks in Tension Stress Fields


wherein the origin size measurement may be very useful for the estimation of fracture toughness.

7.2.4.2 Measure and record the origin depth (a) and, if possible, the width ($2c$) in cases when the origins are inherently surface-distributed, such as machining damage or pits. See Fig. 7. Use the depth (a) in Eq 1 and Eq 2.

NOTE 17—Full characterization to determine the appropriate shape factor (Y) for K_{Ic} calculations requires the width of the origin ($2c$) to be measured in addition to the crack depth (a). See Fig. 7 and the paper by

Raju and Newman listed in X2.8.3 for semicircular or semielliptical surface-crack stress intensity factors.

7.2.4.3 Measure and record the origin diameter ($2a$) if the origin is inherently volume-distributed and is approximately equiaxed, as illustrated in Fig. 6 and Fig. 7. However, use the origin radius in Eq 1 and Eq 2. If a volume-distributed origin is oblong or asymmetrical, report the approximate minor and major axis lengths ($2a$ and $2c$) (for example, a 25 by 60- μm



NOTE 1—A) volume-located;
 B) edge-located;
 C) surface-located; and
 D) near surface-located.

NOTE 2—“FS” denotes the primary fracture surface. All other specimen surfaces are considered external.

FIG. 8 Schematic Which Shows the Four Possible Locations of a Volume-Distributed Fracture Origin.

pore), see Fig. 6 and Fig. 7, and use *half* of the minor axis length in Eq 1 and Eq 2.

7.2.4.4 If fracture mechanics data are available for the particular material, the size of the fracture origin may be estimated using at least one of the following fracture mechanics techniques. The fracture mechanics calculation is used here as a means to verify that the correct feature(s) have been identified as the fracture origin. Compare the measured origin size to the calculated value obtained from Eq 1 or Eq 2. If these values do not agree within a factor of 2 or 3, it is highly recommended that the fracture origin be reexamined to verify that the correct feature(s) have been identified as the origin. If the reexamination shows that the origin has been correctly identified and measured, the variation in these sizes should be noted in the report and explanations given to account for the discrepancy. See Appendix X8 for further information.

7.2.4.5 (a) *Origin Size Estimated from Fracture Toughness or Fracture Energy*—Fracture toughness (K_{IC}) can be used to estimate the size of the fracture origin from Eq 1:

$$a = [K_{IC}/(\sigma Y)]^2 \quad (1)$$

where:

- a = measure of the origin size (that is, depth for a surface crack, or radius or half minor-axis length for a volume-distributed origin, see Fig. 6 and Fig. 7 (m),
- K_{IC} = fracture toughness, $\text{MPa} \sqrt{\text{m}}$,
- σ = fracture stress at the origin location, MPa, and
- Y = stress intensity shape factor for the origin, dimensionless.

Fracture toughness is related to fracture energy for cracks loaded in plane-strain conditions by Eq 2:

$$K_{IC} = [(2E\gamma_f)/(1 - \nu^2)]^{1/2} \quad (2)$$

where:

- E = elastic modulus, MPa,
- γ_f = fracture energy, MN/m or MJ/m², and
- ν = Poisson’s ratio, dimensionless.

and thus:

$$a = (2E\gamma_f)/[Y^2 \sigma^2 (1 - \nu^2)] \quad (3)$$

NOTE 18—In Eq 1, the factor Y incorporates all stress state, specimen, and crack geometric factors. In some references in the literature, Y is used somewhat differently. The fracture mechanics literature should be consulted to find values of Y for specific stress distributions, specimen, and crack geometries. Fig. 7 illustrates several crack geometries and the associated Y factors. The Y factors may vary around the periphery of a crack front. In each instance, the maximum Y should be used. Appendix X2 contains several compilations of stress intensity factors.

NOTE 19—The stress intensity factors in Fig. 7 are for specimens loaded in direct tension. They may be used for origins in flexurally loaded specimens, provided that the origins are small relative to the specimen cross-section size. For flexurally loaded specimens, the stress at the origin location should be used in Eq 1. If the origin is large relative to the specimen cross-section size, consult the references in the Fracture Mechanics section of Appendix X2 for appropriate stress intensity factors.

NOTE 20—Eq 1 can be used to estimate the fracture origin size, but complications often hamper exact calculations. Most origins are too irregular to permit accurate shape factor (Y) determination. Fig. 7 shows some simple crack shapes which can be used for guidance, but these are 2-dimensional cracks which may not adequately match real 3-dimensional origins.

NOTE 21—Eq 1, may be solved for the stress in a component at fracture if the flaw size, the shape factor for the flaw, and the material fracture toughness are known.

NOTE 22—Eq 1 may be solved for the material fracture toughness if the flaw size, the shape factor, and the stress at the origin are known.

7.2.4.6 (b) *Origin Size Estimated from the Fracture Mirror Size*—If a fracture mirror is evident, it can be used to estimate an origin size. The ratio of the outer mirror (mist-hackle boundary) to origin radius is typically 13 to 1 (for glasses, single crystals, and polycrystalline ceramics) and the inner mirror (mirror-mist boundary) ratio is between 10 to 1 (glasses) and 6 to 1 (polycrystalline ceramics).


7.2.4.7 (d) *Component Analysis*—The failure stress in a component may not be known, making it difficult to estimate the origin size using Eq 1 or Eq 2. However, an estimate of the failure stress can be made from the mirror radius according to Eq 4:

$$\sigma = [A/\sqrt{r}] \quad (4)$$

where:

- r = mirror or branching radius, m, and
- A = appropriate mirror or branching constant, $\text{MPa} \cdot \sqrt{\text{m}}$.

The appropriate radius and corresponding constant A in Eq 4 should be used. Use the mirror-mist boundary r_m or r_i (if such exists) with the inner mirror constant (A_i); the mist-hackle boundary r_o with the outer mirror constant (A_o), or the branching distance r_b (where the main crack splits into multiple main cracks) with the branching constant (A_b). A list of mirror and branching constants is given in Appendix X7. Alternately, use Eq 1 if the crack size, the shape factor, and the fracture toughness are known.



NOTE 1—Origin identity and location keys are added for ease in interpretation. The majority of the origins identified in this example are volume-distributed, although as the location column shows some of the individual origins were located at the specimen surface. The fractographic analysis criterion was Level 2 (Materials Development), and thus the location and size were not determined for every specimen. The superscript V stands for inherently volume-distributed origins and the superscript S for inherently surface-distributed origins. In contrast, the V, S, and E designations in the location column refer to the location of the strength-limiting origin in a specific specimen.

NOTE 2—Sintered 99.9 % alumina tested in 4-point flexure, size B, in accordance with Test Method C 1161-90. Weibull parameters estimated with Practice C 1239-93.

FIG. 9 A Labeled Weibull Graph Including a Listing of Strength Values, Identified Origin Types, and Their Associated Locations and Sizes

8. Report

8.1 General—A sample reporting format is shown in Fig. 10. The report shall contain the following information:

- 8.1.1 Fractographer's identity;
- 8.1.2 Equipment used;
- 8.1.3 Overall origin types identified;
- 8.1.4 The inspection criteria in accordance with Table 1;
- 8.1.5 The origin identity, location, size, and the mode of viewing (optical or SEM, or both) for each specimen;
- 8.1.6 Estimated origin sizes from fracture mechanics for each specimen (include the technique used to make such estimates) and a comparison of these estimates to the measured fracture origin sizes;
- 8.1.7 A general statement shall be made regarding the approximate confidence levels for the identity classification of each origin type, or if necessary, each individual origin. (The pores were quite distinct and all classifications are reasonably certain unless appended by the '?' symbol); and
- 8.1.8 Supplemental observations such as transgranular or intergranular fracture (or the approximate ratio of each) in the


vicinity of the origin (inside the mirror) and outside the fracture mirror, fracture mirror measurements, and the criteria used to measure them, if such information is available.

8.2 To the extent possible, couple the fractographic observations directly to process history and resultant microstructure. Representative micrographs of polished sections of the microstructure showing porosity and grain size distribution are highly recommended.

8.3 Couple the fractographic observations directly to the mechanical test results. Fractographic montages and labeled Weibull or other strength graphs (Fig. 9 and Fig. 11) are an exceptionally versatile means of accomplishing this. Montages present the fractographic results in a comprehensive manner.

9. Keywords

9.1 advanced ceramics; flaws; fractography; fracture mechanics; fracture mirrors; fracture origins; microscopy



Fractography Montage

NOTE 1—Calculations of mirror and origin sizes, fracture mechanics estimates, and other information can be made in the sides and margins of this worksheet. A photograph of microstructure including porosity and grain size should also be included on the montage as illustrated on the lower right.


FIG. 11 A Schematic of a Working Fractographic Montage Linking Fractographs and Strength Plot

APPENDIXES

(Nonmandatory Information)

X1. EXAMPLES OF FRACTURE ORIGINS IN ADVANCED CERAMICS

X1.1 See Figs. X1.1-X1.15.




MATERIAL: Sintered (99.9% pure) Alumina, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 337$ MPa

(P^r, S, 35μm)




MATERIAL: Sintered Yttria-tetragonal zirconia polycrystal, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature after being exposed to ≈ 850 Pa water vapor pressure at 200C for 50 hours

COMMENTS: $\sigma = 544$ MPa

(P^r, V, 125μm)



MATERIAL: Sintered Yttria-tetragonal zirconia polycrystal, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 594$ MPa

(P^r, NS, 40 x 60μm)

FIG. X1.1 Examples of Pores






FIG. X1.2 Examples of Porous Seams



MATERIAL: Sintered (99.9% pure) Alumina, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature


COMMENTS: $\sigma = 430$ MPa
(PR², S, 35 μ m)



MATERIAL: Sintered (99.9% pure) Alumina, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 419$ MPa;
-Flaw is a zone of concentrated microporosity
(PR², S, 60 μ m)




MATERIAL: Sintered SiAlON with Yttria & Alumina additions, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 450$ MPa
(PR², S, 50 x 60 μ m)


FIG. X1.3 Examples of Porous Regions



MATERIAL: Sintered α -Silicon Carbide, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 362$ MPa;
-The formation of the agglomerate can be traced to the spray drying process used to manufacture the starting powder
(A*, S, 50 μ m)



MATERIAL: Sintered Yttria-Tetragonal Zirconia Polycrystal, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 765$ MPa;
-Photos show the mating halves of the fracture surface
(A*, S, 50 μ m)




FIG. X1.4 Examples of Agglomerates




FIG. X1.5 Examples of Inclusions






FIG. X1.6 Examples of Compositional Inhomogeneities



MATERIAL: Siliconized Silicon Carbide, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature


COMMENTS: $\sigma = 169$ MPa;
 -Flaw is large grains of Silicon Carbide
 -Interpretation was aided by photographs of a representative polished section
 (LG^o, S, 125 μ m)



MATERIAL: Sintered (99.9% pure) Alumina, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 404$ MPa;
 -Large grains in this particular specimen are located near the edge
 (LG^o, R, 7)




MATERIAL: Hot-pressed Alumina reinforced with Silicon Carbide whiskers, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature after being exposed to 1000C for 500 hours

COMMENTS: $\sigma = 220$ MPa
 (LG^o, S, 20 x 30 μ m)

FIG. X1.7 Examples of Large Grains




MATERIAL: Not-pressed Yttria-Tetragonal Zirconia Polycrystal, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature after being exposed to = 800 Pa water vapor pressure 200C for 50 hours

COMMENTS: $\sigma = 514$ MPa

(C^o, S, T)




MATERIAL: Sintered β -Silicon Carbide, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 340$ MPa;
-Optical photo of the tensile surface of a flexure bar showing a crack in the material (large white arrows)

-Failure originated on the tensile surface at the point marked by the small white arrow

(C^o, S, T)




MATERIAL: Not isostatically pressed Yttria-Tetragonal Zirconia Material, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature after being exposed to 1000C for 500 hours

COMMENTS: $\sigma = 973$ MPa;
-This could be a pore that collapsed during the HIPing process

(C^o, V, 60μm)

FIG. X1.8 Examples of Cracks





MATERIAL: Sintered Reaction-Bonded Silicon Nitride, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 409$ MPa
Parallel machining crack from a coarse grit wheel transverse direction

(MD, S, 65 x 450 μ m)





MATERIAL: Sintered Reaction Bonded Silicon Nitride as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 542$ MPa
Parallel machining crack from transverse grinding, 320 grit
20 – 25 μ m deep
Note the fingerlets projecting upwards in this "zipper crack" as well as the flattened mirror shape.

(MD, S, 25 x 180 μ m)



MATERIAL: Sintered silicon carbide as-machined

TEST CONDITIONS: fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 240$ MPa.


A parallel machining crack stands out clearly even in these low magnification optical photos
220 grit centerless

(MD, S, 35 x 300 μ m)

FIG. X1.9 Examples of Machining Damage




FIG. X1.10 Examples of Machining Damage (See Fig. X1.9)



MATERIAL: Sintered Sialon with Yttria & Alumina additions, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature


COMMENTS: $\sigma = 595$ MPa;
-Scratch on the tensile surface
(HD², S, 7)



MATERIAL: Reaction-bonded Silicon Nitride, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 257$ MPa;
-Side view of a flexure bar showing a scratch (black arrows) which caused fracture at the chamfer
(HD², S, 7)




MATERIAL: Sintered (99.9% pure) Alumina, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 387$ MPa;
-Hertzian cone crack from impact damage
(HD², S, 7)


FIG. X1.11 Examples of Handling Damage



MATERIAL: Hot-pressed Silicon Nitride with Magnesia additions, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature after being exposed to 1000C for 500 hours


COMMENTS: $\sigma = 598 \text{ MPa}$;
-Pits formed due to oxidation
(PT², S, 20 μm)



MATERIAL: Hot-pressed Silicon Nitride with Magnesia additions, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature after being exposed to 1000C for 500 hours in a corrosive environment

COMMENTS: $\sigma = 292 \text{ MPa}$;
-Pit formed as a result of corrosion
-The pit contains Na from the sodium sulfate corrosion material
(PT², S, 120 μm)




MATERIAL: Reaction-bonded Silicon Nitride, as-machined

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature after exposure to a severe cycling sequence involving oxidation heat treatments & thermal cycling in a gas torch

COMMENTS: $\sigma = 223 \text{ MPa}$;
-The exposure has caused the chamfer region to round
(PT², B, 20 μm)

FIG. X1.12 Examples of Pits




MATERIAL: Injection Molded & Sintered Silicon Nitride with Yttria & Alumina additions, as-fired

TEST CONDITION: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 472$ MPa;
-Photo shows both halves of the fracture surface

(SV^o, S, 40μm)




MATERIAL: Injection Molded & Sintered Silicon Nitride with Yttria & Alumina additions, as-fired

TEST CONDITIONS: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 515$ MPa

(SV^o, S, 50μm)




MATERIAL: Injection Molded & HIP'ed without a cladding, Silicon Nitride with Yttria & Alumina additions, as-fired

TEST CONDITION: Fast fracture in 4-point flexure at room temperature

COMMENTS: $\sigma = 476$ MPa;
-Surface pore is flattened at the edges since there was no cladding

(SV^o, S, 25μm)

NOTE 1—Courtesy of A. Pasto, GTE Laboratory, now with Oak Ridge National Laboratory.
FIG. X1.13 Examples of Surface Voids



MATERIAL: Siliconized Silicon Carbide, as-machined

TEST CONDITION: Fast Fracture in 4-point flexure at room temperature after exposure to 1000°C for 500 hours

COMMENTS:

- Photo shows both fracture halves mounted back to back on the tensile surface (middle of photo)
- Flaw is a vein of elemental Si
- $\sigma = 282$ MPa

FIG. X1.14 Examples of Less Common Other Flaws




FIG. X1.15 Examples of Flaws with Mixed Attributes

X2. A SELECT BIBLIOGRAPHY ON FRACTOGRAPHY AND ORIGINS IN CERAMICS

INTRODUCTION

The references listed as follows are included for the benefit of users who wish to inquire further about fractography of ceramics in general, microscopic techniques, fracture origins and flaws in advanced ceramics, fracture mirrors, and fracture mechanics and its application to advanced ceramics.

X2.1 Books and Articles on Advanced Ceramics Fractography

X2.1.1 Frechette, V. D., *Failure Analysis of Brittle Materials, Advances in Ceramics*, Vol 28, American Ceramic Society, Westerville, OH, 1990.

X2.1.1.1 A must for the serious fractographer. This book covers all aspects of the fractography of glasses including fundamental markings on crack surfaces (Wallner lines, hackle, and so forth), crack forking, failure origins, estimates of stress at fracture and fractographic techniques. Superbly illustrated with a number of service failures and case histories presented.

X2.1.2 Rice, R. W., "Topography of Ceramics," in *Surfaces and Interfaces of Glass and Ceramics*, Frechette, V., LaCourse, W., and Burdick, V., eds., Plenum Press, NY, 1974, pp. 439–472.

X2.1.2.1 A very helpful introduction describes the role of unaided eye, hand lens, optical, scanning, and transmission electron microscopy. Fig. 1 shows optical and SEM photos of the same origin. Fracture surface features such as transgranular and intergranular fracture, crack microstructure interactions, crack branching, mirrors, and single crystal fractography are discussed.

X2.1.3 Rice, R. W., "Ceramic Fracture Features, Observations, Mechanism and Uses," *Fractography of Ceramic and Metal Failures, ASTM STP 827*, ASTM, 1984, pp. 5–103.

X2.1.3.1 A lengthy review paper with a detailed technical discussion of fracture mirrors and related features (mist, hackle, and branching) in glasses, polycrystals, and single crystals. The "bluntness" of origins (round pores versus sharp machining cracks) will alter the mirror-to-origin radius ratio. A useful table of branch angle as a function of mode of loading (flexure, tensile, biaxial, thermal) for several materials is given.

X2.2 Microscopic Techniques

X2.2.1 Pantano, C. G., and Kelso, J. F., "Chemical Analysis of Fracture Surfaces," *Fractography of Ceramic and Metal Failures, ASTM STP 827*, ASTM, 1984, pp. 139–156.

X2.2.1.1 The applicability of various instrumental techniques for chemical analysis of fracture surfaces is reviewed. The relative merits and spatial and depth resolutions of Auger microscopy and energy or wavelength dispersive electron microscopy are given.

X2.2.2 Healy, J. T., and Mecholsky, Jr., J. J., "Scanning Electron Microscopy Techniques and Their Application to Failure Analysis of Brittle Materials," *Fractography of Ceramic and Metal Failures, ASTM STP 827*, ASTM, 1984, pp. 157–181.

X2.2.2.1 Discusses cleaning, coating, and other procedures for SEM specimens. The merits and differential emphases of secondary and backscattered electron imaging are presented.

X2.2.3 "Fractography," *Metals Handbook*, 9th ed., Vol 12, ASM, Metals Park, OH, 1987.

X2.2.3.1 An excellent handbook on fractography of metals. Some generic sections including photographic, optical inspection, and electron microscopy techniques are directly applicable to ceramic fractography. Light, secondary electron, and backscattered electron photos of identical locations in metal specimens are compared. **Caution:** Some cleaning and preparation techniques such as surface coatings, replicating tapes, replicating tape stripping, and aggressive detergent cleaning which are prescribed for metals are not recommended for ceramic fracture surfaces.

X2.3 Fracture Mechanics—Stress Intensity Factors

X2.3.1 *Stress Intensity Factors Handbook*, Vols 1 and 2, Murakami, Y., ed., Pergamon Press, NY, 1986.

X2.3.2 Rooke, D. P., and Cartwright, D. J., *Compendium of Stress Intensity Factors*, Her Majesty's Stationary Office, London, 1976.

X2.3.3 Newman, Jr., J. C., and Raju, I. S., "An Experimental Stress-Intensity Factor Equation for the Surface Crack," *Engineering Fracture Mechanics*, Vol 15 [1–2], 1981, pp. 185–192.

X2.3.3.1 Presents an equation for the calculation of the shape factor (Y) for origins which are essentially semicircular or semielliptical and located at the surface. The Y is determined where the origin meets the surface and at the deepest point of the origin. The highest value is then used in fracture mechanics calculation.

X2.3.4 Tada, H., Paris, P. C., and Irwin, G. R., *The Stress Analysis of Cracks Handbook*, Del Research Corp., St. Louis, MO, 1973.

X2.3.5 Bar-on, I., "Applied Fracture Mechanics," *Engineered Materials Handbook*, Vol 4, *Ceramics and Glasses*, Schneider, S., ed., ASM, Metals Park, OH, 1991, pp. 645–651.

X2.3.5.1 A good primer on the applications of fracture mechanics analysis to idealized crack configurations. Stress intensity shape factors are given for through slits, surface cracks, and pores with rim cracks.

X2.3.5.2 Tada, H., Paris, P. C., and Irwin, G. R., *The Stress Analysis of Cracks Handbook*, 3rd edition, ASM International, Metals Park, OH 2000.

X2.3.5.3 Fett, T. and Munz, D., *Stress Intensity Factors and Weight Functions*, Wessex Institute of Technology, Southampton, UK, 1997.

X2.3.5.4 Sih, G. C., *Handbook of Stress Intensity Factors*, Lehigh University, Bethlehem, PA, 1973.

X3. SYNOPSIS OF ARL-TR-656

X3.1 This practice was derived from MIL HDBK-790 (Fractography and Characterization of Fracture Origins in Advanced Ceramics) which was prepared by G. D. Quinn, J. J. Swab, and M. J. Slavin. A round-robin exercise sponsored by the Versailles Project on Advanced Materials and Standards (VAMAS) was conducted to determine the applicability of Military Handbook 790 and to attempt to clarify any ambiguous sections or issues. The round robin included both photo and specimen examination and interpretation. The final report of this round-robin is ARL-TR-656, "Fractography of Advanced Structural Ceramics: Results from the VAMAS Fractography Round Robin Exercise," which was also published as Versailles Project on Advanced Materials and Standards (VAMAS) Report No. 19, in February 1995. These reports are on file at ASTM International Headquarters as research reports for this practice. See Refs (2-4).


X3.2 The guidelines and characterization scheme outlined in the earlier handbook were adequate to completely characterize fracture origins in ceramics, but some refinements were necessary. Although there was a good to excellent consensus in many cases in the round robin, the instances where concurrence was not forthcoming prompted the Committee to include the following recommendations or requirements in this practice. Since machining damage is often difficult to detect, this practice has additional guidance and illustrations. This practice also has additional guidance on how to utilize fracture mechanics as an aid to fractographic analysis. Fractographers are cautioned to use all available information about the material and its processing and exposure history. Fractographers should look at both mating halves of the fracture surface and also should examine the external surfaces of the specimens or component if the origin is located on a surface.

X4. FRACTOGRAPHIC EQUIPMENT

X4.1 See Figs. X4.1-X4.5.



FIG. X4.1 Binocular Stereomicroscope with Directionally Adjustable Fiber-Optical Light Source and Variable Magnification Between 5 and 80 \times .



NOTE 1—This type of system is excellent for instructional purposes.

FIG. X4.2 Dual Station, Binocular Stereomicroscope with Two Directionally Adjustable Light Sources, Video Camera, Monitor, and Instant Photographic Capability



FIG. X4.3 Scanning Electron Microscope with Energy Dispersive Spectroscopic Capabilities, Low-Energy Operation, and Magnification Between 20 and 20 000×



NOTE 1—(A) Hand-held and tabletop magnifying glass; (B) Variable-angle grips with compliant surface; (C) Fixtures to support specimens to view machined surfaces; (D) Compressed air; (E) Tweezers for specimen manipulation; (F) Plastic storage trays; (G) Glass vials for storage of fractured specimens prior to SEM analysis.

FIG. X4.4 Peripheral Equipment to Assist in Fractography and Storage of Fractured Specimens and Components





FIG. X4.5 Macrophotographic Camera Stand for Instant Photographs


X5. COMMON CONTAMINANTS ON CERAMIC FRACTURE SURFACES

X5.1 See Figs. X5.1-X5.5.




NOTE 1—These typically appear as globules, but since pencil graphite usually has a clay binder, it must be treated with caution.

FIG. X5.1 Contamination from Particles of Graphite from a Common Leaded Pencil




NOTE 1—Masking tape is sometimes used to hold pieces of a fractured specimen together, but should be avoided on the fracture and tensile surfaces. The smear blends into the fracture surface and is partially transparent to X rays as shown. An energy dispersive analysis identified the smear as having potassium, chlorine, and sulfur. Trichloroethylene is an effective solvent to remove the resin.

FIG. X5.2 Contamination from a Smear of Masking Tape Resin (White Arrows) Near a Chamfer



NOTE 1—These are easy to blow off or eliminate by a sonic bath.
FIG. X5.3 Contamination from Particles of Paper Lint (Black Arrows) from a Common Manila Specimen Envelope



NOTE 1—What might be the most pernicious contaminant in the fractographic laboratory: mounting clay. The white arrows in (a) show a region where clay was dabbed on with tweezers. The clay appears to be a genuine inclusion that blends directly into the underlying ceramic. It is extremely difficult to remove once it gets onto the specimen and it looks quite appropriate on the fracture surface. It should not be used. (b) is a close-up of the region of the small arrow from (a). An energy-dispersive analysis revealed silicon, aluminum, and titanium. The Si is indistinguishable from the silicon nitride specimen.

FIG. X5.4 Contamination from Mounting Clay







FIG. X5.5 Contamination from Human Skin (Courtesy of A. Pasto,

GTE Laboratory, now with Oak Ridge National Laboratory)

X6. TYPICAL FRACTURE PATTERNS IN CERAMIC TEST SPECIMENS

X6.1 See Fig. X6.1 and Fig. X6.2.



A SECONDARY FRACTURE CAUSED BY THE ELASTIC RELEASE WAVE - REFLECTION OFF OF THE END FACES. NOTE THIS OFTEN OCCURS AT LOAD PINS. NOTE THE MIRROR IS ON WHAT ORIGINALLY WAS THE COMPRESSION SIDE.








FIG. X6.1 Typical Fracture and Crack Patterns of Flexure Specimens





FIG. X6.2 Typical Fracture and Crack Patterns of: (a) Biaxial Flexure Specimens and (b) Diametral Compression Specimens

X7. MIRROR AND BRANCHING CONSTANTS FOR GLASSES AND ADVANCED CERAMICS

X7.1 Table X7.1 lists published fracture mirror constants for a range of glasses and ceramics. The table includes A_i , the inner mirror constant for the mirror-mist boundary; A_o , the outer mirror boundary for the mist-hackle boundary; and A_b , the branching constant. This listing is in the same order as the sequence of formation of the boundaries.

X7.1.1 There often is considerable variability in the published values for the parameters even for identical glasses. This is due in large part to the lack of consistent guidelines or procedures and techniques for determining constants. Different specimen geometries, test techniques (flexure, tension), specimen types (rods, bars, disks), microscopy and illumination procedures, radii measurement directions, and mathematical analyses were used. Some judgment is involved in assessing a boundary location, especially for polycrystalline ceramics. Inner mirror constants are not often evaluated for polycrystalline ceramics since mist, if it exists, cannot be discerned against the microstructure. Residual stresses can dramatically alter apparent mirror constants. In most instances fracture strength and mirror radius data were curve fitted with particular functions such as stress versus inverse square root of mirror radius, or alternatively log stress versus log radius. Residual stresses cause a non-zero intercept in the former graphs or a slope different than -0.5 in the latter. Data in the table below that has been fitted with equations other than equation 4 ($\sigma = A/\sqrt{r}$) often have very different mirror constants than the other entries. Such data is marked with an asterisk in the table. The user should consult the original reference for additional information.

X7.1.2 The constants have the same dimensions as fracture toughness: $\text{MPa}\sqrt{\text{m}}$. The numerical value of the mirror constant is always greater than the fracture toughness. For glasses and polycrystalline ceramics, the outer mirror boundary (mist/hackle) constant is typically 3 times larger, but can range from 2 times to 5 times larger than the fracture toughness. Inner mirror boundary (mirror/mist) constants are 2 times to 3 times larger than fracture toughness for polycrystalline ceramics, but are typically 3 times larger for glasses.

X7.1.3 The mirror and branching constants are usually independent of the origin flaw type, stressing rate, presence or absence of slow crack growth, stress level, and test duration (fast fracture or delayed fracture – stress rupture). The constants A_i and A_o are usually independent of the stress state (uniaxial, biaxial, tension, flexure) provided that the mirror size is small relative to the specimen cross-section size. The branching constant does show a dependency on stress state. For uniaxial loadings $A_b > A_o$, but for equibiaxial loadings A_b approaches A_o .

X7.1.4 Estimates of mirror and branching constants are very sensitive to residual stresses. Estimates also may be sensitive to the size of the mirror relative to the component cross-section size.

X7.1.5 In all instances, the stress *at the origin of fracture* should be used with Eq 4

TABLE X7.1 List of Published Fracture Mirror and Branch Constants

NOTE—All values are listed to the same number of significant figures as shown in the original reference. Uncertainties (\pm one standard deviation) are listed when available from the original reference. Multiple entries in a cell denote estimates by different microscopy techniques or analysis. For polycrystalline ceramics, the mirror constants taken from the reference sources are assumed to be for the mist-hackle unless otherwise stated.

Material	Technique	Mirror-Mist A_i ($\text{MPa}\cdot\sqrt{\text{m}}$)	Mist-Hackle A_o ($\text{MPa}\cdot\sqrt{\text{m}}$)	Branching A_b ($\text{MPa}\cdot\sqrt{\text{m}}$)	Ref
Glasses:					
Flint (Kimble R6 soda lime)	Flexure (Rods)		2.0		8
Flint (Kimble R6 soda lime)	Flexure (Rods)		1.9		9
Flint (Kimble R6 soda lime)	Flexure (Rods)		2.3		10
Soda-Lime Silicate – window glass	Flexure (biaxial ring-on ring, large)		2.09		26
Soda-Lime Silicate – window glass	Pressurized windows, large	1.96			39
Soda-Lime Silicate	Flexure (Bars)		1.74		14
Soda-Lime Silicate A—plate glass	Flexure (Bars – large)	1.86 ± 0.66			27
Soda-Lime Silicate B—plate glass	Room Temperature to Strain Point	1.82 ± 0.91			
Soda-Lime Silica Float	Flexure (Bars)	1.80 ± 0.15	2.42 ± 0.16		40
Soda-Lime Silica Float (G.E.C. – X8)	Tension (Rods)	1.89 ± 0.06	2.04 ± 0.06		7
	Flexure (Bars)		2.09		
Soda-Lime Silica Float	Flexure (Bars)	1.92	2.21		18,21
	Flexure-Delayed failure (Bars)	2.0 ± 0.1	2.2 ± 0.1		21
Soda Lime Silica Float	Flexure (Bars, large and small)	2.06 ± 0.07	2.29 ± 0.19		16
Soda-Lime Silica	Tension (Plates)			1.2 - 1.6	12
Soda-Lime Silica	Flexure (Bars)			3.54 ± 0.64	33
	Flexure (Biaxial ring-on-ring plates)	1.81 ± 0.28			
Soda-Lime Silica	Tension			1.9	34
Soda-Lime Silica	Pressurized Tube			2.0	35
Soda-Lime Silica	Flexure (Biaxial ring-on-ring disks)	1.82 - 1.94	2.03 - 2.13	2.28 - 2.42	19
	3 environments				
Soda-Lime Silica	Flexure (Biaxial ring-on-ring disks)			2.1^A	15

TABLE X7.1 *Continued*

Material	Technique	Mirror-Mist A_i (MPa· \sqrt{m})	Mist-Hackle A_o (MPa· \sqrt{m})	Branching A_b (MPa· \sqrt{m})	Ref
Borosilicate A (P 3235)	Flexure (Bars – large)	1.98 ± 0.46			27
Borosilicate B (C 7740)	Room Temperature to Strain Point	2.04 ± 0.75			17,18
Borosilicate (C 7740)	Flexure (Bars)	1.87 ± 0.3	2.10		20
Borosilicate (C 7740)	Flexure (Bars) and Biaxial disks)	1.9 ± 0.3			25
Borosilicate crown (S BK-7)	Flexure (Biaxial ring-on ring disks) ^A	1.98 ± 0.02 ^A	2.11 ± 0.03 ^A	2.28 ± 0.03 ^A	
			2.3		
Aluminosilicate (C 1723)	Flexure (Bars)	2.14	2.40		18
Aluminosilicate A (P 6695)	Flexure (Bars – large)	2.31 ± 0.76			27
Aluminosilicate B (C 1723)	Room Temperature to Strain Point	2.34 ± 0.97			7
Lead silicate (G.E.C. L1)	Tension (Rods)	1.71 ± 0.06			18
Lead Silicate	Flexure (Bars)	1.61	1.78		18
Fused Silica (C 7940)	Flexure (Bars)	2.23	2.42		18
Fused Silica (C 7940)	Flexure (Bars—large; Room Temperature to Strain Point)	1.89 ± 0.51			27
Fused silica (Vitreosil)	Tension (Rods)	2.33 ± 0.06			7
Fused silica	Flexure (Rods)	2.20 ± 0.33			33
Fused silica fibers	Tension	2.10			33
Fused silica clad fibers	Tension	1.96 ± 0.13			30
Fused silica fibers, bars, disks	Tension (Fibers)	2.2 ± 0.5			20
	Flexure (Bars)	2.3 ± 0.5			
	Flexure (Biaxial, piston on 3 balls)	2.4 ± 0.3			
Fused silica fibers	Tension	2.224			37
Leached High Silica (C 7930)	Flexure (Bars)	0.91	1.19		18
96 % Silica (C 7900)	Flexure (Bars – large)	1.84 ± 0.65			27
	Room Temperature to Strain Point				
Glassy Carbon	Flexure (Bars)	1.17	1.67		17,18
As ₂ Se ₃ chalcogenide glass, untreated	Tension	0.69	0.77		45
As ₂ Se ₃ chalcogenide glass, UV treated		0.35	0.38		
As ₂ S ₃	Flexure (Bars)	0.56	0.65		18
Ge ₃₃ As ₁₂ Se ₅₅	Flexure (Bars)	0.55	0.65		18
0.3PbSe - 0.7Ge _{1.5} As _{0.5} Se ₃	Flexure (Bars)	0.48	0.55		18
Glass Ceramics:					
Pyroceram 9608 (Li, Mg, alumino silicate) NR			2.8		28
Pyroceram 9607 (Li, Mg, Zn alumino silicate) NR			2.1 ^A		28
Pyroceram 9606 (Cordierite, Mg alumino sili- Flexure cate)		3.6	6.5		17
Pyroceram 9606 (Cordierite, Mg alumino sili- Flexure (Bars) cate)			6.5		44
Pyroceram 9606 (Cordierite, Mg alumino sili- Flexure (Bars) cate)			5.7		13,14
Pyroceram 9606 (Cordierite, Mg alumino sili- Flexure (Bars) and cate)	Flexure (Biaxial, piston on 3 balls)		6.3		20
Pyroceram 9606 (Cordierite, Mg alumino sili- Flexure (Biaxial, ring on ring) cate)				3.1 ± 0.2 ^A	15
Li ₂ O-SiO ₂ (NPL glass ceramic, 2 grades)	Flexure (Bars)	3.3, 3.8	4.5, 5.4		17
Dicor (dental, tetra silica fluoromica)	Flexure (Bars)		0.97		47
Silicon Carbide:					
Sintered SiC (Hexoloy SA)	Flexure (Bars)		5.39		23
Sintered SiC (Hexoloy SA)	Flexure (Biaxial ring-on-ring plates)			6.30 ± 0.54	31
Sintered SiC (Hexoloy SA)	Flexure (Biaxial ring-on-ring plates)			5.45 ± 0.30	33
Sintered SiC toughened (Hexoloy SX)	Tension (Rods) and Flexure (Bars)		7.0?	7.0?	42
Sintered (Carolt S)	Flexure (Bars, optical, SEM)		6.1, 6.8		36
Hot-pressed SiC (NC-203)	Flexure (Rods)		11.4		8
	Flexure-Delayed Fracture (Rods)		11.9		
Hot-pressed SiC (NC-203)	Flexure (Rods)		11.5		9
Hot-pressed SiC (ACE)	Flexure (Rods)		10.8		10
Siliconized SiC (KT)	Flexure		10.7		17
Zirconia:					
Yttria stabilized (Y-TZP)	Flexure (Bars)		9.95		43
Yttria stabilized (Y-TZP)	Flexure (Biaxial ring-on-ring disks)			11.48 ± 1.46	33
Zircar (Alfred-Union Carbide, 0.4 μm)	Flexure (Bars)		15.2		17
Zyttrite (AFML, 10 μm)	Flexure (Bars)		7.4		17
Silicon Nitride:					
Sintered Reaction Bonded (Ceraloy 147-31N)	Flexure (Rods)		8.47 ± 0.07		22
	Flexure (Bars)		7.79 ± 0.02		
Sintered (SSN-500 yttria/alumina)	Flexure (Bars)		5.81		23
Sintered (SN 220)	Flexure (Biaxial ring-on-ring disks)			8.13 ± 2.36	33
Sintered (AS 44)	Flexure (Biaxial ring-on-ring disks)			10.85 ± 2.71	33

TABLE X7.1 *Continued*

Material	Technique	Mirror-Mist A_i (MPa· \sqrt{m})	Mist-Hackle A_o (MPa· \sqrt{m})	Branching A_b (MPa· \sqrt{m})	Ref
Hot-pressed (Ceraloy 147A)	Flexure (Bars)		7.83		23
Hot-pressed (NC-132)	Flexure (Rods)		9.2		9
Hot pressed (NC-132)	Flexure (Rods)		8.9		8
	Flexure-Delayed Fracture (Rods)		9.2		
Hot-pressed (NC-132)	Flexure (Rods)		14.3		10
Hot-pressed (NC-132)	Flexure (Bars)		9.40 ± 1.19		33
	Flexure (Biaxial ring-on-ring)			7.92 ± 2.08	
Hot-pressed (HS-130)	Flexure		18.1		17
Hot-pressed (HS-130)	Flexure (Rods)		9.1		8
Hot-isopressed (NT 154)	Flexure (Bars)		5.88 ± 0.14		32,33
Hot-isopressed + 30vol % SiC whiskers	Flexure (Bars)		6.63 ± 0.11		32,33
Hot-isopressed (GN-10)	Flexure (biaxial ring-on-ring)			10.32	33
	Tension (Rods)		11.78 ± 1.41		
Reaction Bonded (NC 350)	Flexure (Bars)		3.89		24
Reaction Bonded (NC 350)	Flexure (Bars)		3.19		29
Reaction Bonded (AME A25B)	Flexure (Rods)		4.2		8
Alumina:					
Sapphire (average of several planes)	Flexure		6.1		17
Sapphire (Tyco filaments, C-axis parallel to fiber axis)	Tension		5.5		38
	Flexure		10.0		
Sapphire (Ruby rods, C axis -60° off rod axis)	Flexure (Rods)		3.3		38
β -Al ₂ O ₃	Flexure		~ 6.5		17
Hot-pressed (99+ % pure,Cer. Fin.)	Flexure (Rods, 4-point)		10.3		8,9
	Flexure-Delayed Fracture (Rods, 4 pt.)		9.9		8
Hot-pressed (99+ % pure,Cer. Fin.)	Flexure (Rods-3 point)		9.1		10
Hot-pressed (99+ % pure)	Flexure	5.2	12		17
Hot pressed	Flexure (Rods)		10.4		11
Hot-pressed	Flexure		9.8		14
Sintered (Lucalox)	Tension (Plates)			7.3	12
Sintered (96 %) (Alsimag 614)	Flexure (Rods)		8.5		9
Sintered (96 %) (Alsimag 614)	Flexure (Rods)		8.3		8
	Flexure-Delayed Fracture (Rods)		8.9		
Sintered (96 %) (Alsimag 614)	Flexure (Bars)		9.0		13,14
Sintered (96 %) (Alsimag 614)	Flexure (Rods)		9.1		10
Sintered (96 %) (Alsimag 614)	Flexure (Bars)		13.1		17
Sintered (96 %) (Alsimag 614)	Flexure (Bars)		7.64 ± 0.53		33
	Flexure (Biaxial ball-on-ring)			7.39 ± 0.55	
	Flexure (Biaxial ring-on-ring)			7.24 ± 0.66	
Sintered 96 % (Alsimag 614)	Flexure (Biaxial ring-on-ring disks)			4.0 ± 0.28 ^A	15
Other:					
Ammonium diphosphate, single crystal	Flexure (Bars)		0.5		17
WC-Co	Flexure		24-87		41
WC (no Co)	Flexure		10		46
Mullite	Flexure		6.1		17
MgO	Flexure		9.6		17
MgO	Tension (Plates)			4.3	12
MgO, single crystal	Flexure (Bars)		5		17
MgF ₂ (Kodak)	Flexure (Bars)	1.8	3.1		17
MgF ₂ (Kodak, IRTRAN 1)	Flexure (Bars) and Biaxial Disks			4.4	20
MgAl ₂ AlO ₄ Spinel	Flexure (Bars)	4.0	7.8		17
MgAl ₂ AlO ₄ Spinel, single crystal	Flexure (Bars)		2.6		17
B ₄ C hot-pressed	Flexure (bars)	4.8	9.27		17
3BaO-SiO ₂	Flexure (Bars)	3.9	6.0		17
PZT	Flexure	1.7	3.7		17
Graphite (POCO)	Flexure		3.32		17
BaTiO ₂ (2 grades)	Flexure (Bars)		5.0, 5.4		17
SrZrO ₃	Flexure (Bars)	4.4	6.0		17
Steatite (magnesium silicate insulator DC -144)	Flexure (Rods)		4.8		8,9
					10
			4.5		
Zircon Porcelain (Alsimag 475)	Flexure (Rods)		4.0		8,9
Feldspathic Porcelain (alumina filled, Vitadur N 338)	Flexure (Bars)		2.82		47
ZnSe	Flexure (Bars)			1.7	17

^A A non-zero intercept was detected on the graph of stress versus inverse square root radius. Mirror or branching constants calculated with non-zero intercepts are usually different than those calculated with intercepts through the ordinate. Consult the original reference for more information..

X8. COMPLICATIONS IN COMPARING CALCULATED AND MEASURED ORIGIN SIZES

X8.1 Fracture mechanics should be used routinely to support fractographic analyses. This practice includes a fracture mechanics check on the identified fracture origin. Verification is considered adequate if the calculated and fractographically measured sizes agree within a factor of two or three. If the sizes disagree, the fractographer should reconsider his or her characterization of the origin. Either the wrong feature has been identified as the origin or the origin may be more complicated than expected. Size discrepancies may arise from a variety of sources discussed below. Specifics and examples of these complicating factors can be found in the references listed in Table X8.1.

X8.2 c_{calc} is sometimes larger than c_{meas} since the measured flaw was a fracture initiating flaw that subsequently extended by subcritical crack growth, either from R-curve or environmental causes, or by flaw link-up. This highlights an important distinction between a “fracture initiating flaw” and the “critical flaw.” These may or may not be equal.

X8.3 Additional information and examples are in Refs (4-6).


TABLE X8.1 Complicating Factors

Factors That Cause $c_{calc} < c_{meas}$	Factors That Cause $c_{calc} > c_{meas}$	Factors That Cause Either $c_{calc} > c_{meas}$ Or $c_{calc} < c_{meas}$
Crack Blunting	Stable Crack Extension—Environmentally Assisted	Multiple Crack Nesting or Interaction
Use of 2-Dimensional Crack Models	Stable Crack Extension—R Curve Phenomena	Stable Crack Extension—High Temperature
Specimen or Component Stress Gradients	Specimen or Component Stress Raisers	Residual Stresses
	Origin Causes A Local Fracture Toughness Degradation	Origin Truncation on the Fracture Surface
	Origin is Within a Single Grain	Origin Shape Irregularity
	Origin Link-up With Other Flaws or a Surface	Variations Between the Properties of the Origin and Surrounding Matrix
		Faulty Fracture Toughness Data

X9. SCHEMATICS OF MACHINING DAMAGE CRACKS IN CERAMICS AND GLASSES

X9.1 Diamond grinding may create strength limiting machining cracks. Fig. X9.1 shows two of the primary crack types: orthogonal and parallel cracks. The names refer to the direction of the crack plane relative to the grinding direction. The bar and rod specimens shown on the bottom illustrate how the orthogonal or parallel cracks may or may not be activated during a flexural strength test. In Fig. X9.2, fractographic manifestations of machining damage or scratch damage strength limiting flaws or longitudinally-ground specimens. The schematics show the fracture surface but with the test


piece tilted back so that a portion of the ground surface and its striations are visible. Parallel machining cracks are often difficult to detect against the microstructural features of polycrystalline ceramics. In Fig. X9.3, fractographic manifestations of machining damage strength limiting flaws for transversely-ground or scratched specimens. The schematics show the fracture surface but with the test piece tilted back so that a portion of the ground surface and its striations are visible. Parallel machining cracks are much easier to detect than orthogonal machining cracks.



NOTE 1—The machining cracks extend much deeper into the bulk than the striation-grooves on the surface.


FIG. X9.1 Schematic of Machining Crack Damage

Cracks induced by machining, polishing, or scratching extend well below the finished surface. Traces on the finished surface may not even be present if they have been removed by subsequent grinding or polishing. Cracks may be as shallow as 5 μm in polished glass or as deep as 50 μm -100 μm in scratched or coarse ground surfaces. Surface grinding usually produces cracks of the order of 15 μm – 60 μm deep depending upon the grinding conditions. Telltale features of fracture origins and mirrors associated with machining damage are depicted in the schematics below. In each instance the specimen is tilted back to show part of the finished surface as well as the fracture surface. The schematics show the entire fracture mirror for high strength specimens wherein the mirror is small relative to the specimen size and any possible stress gradients. Mirrors are incomplete, flared out, or elongated into the test piece interior (depth) in low to medium strength fractures in bending fractures (not shown).




LONGITUDINALLY GROUND SURFACES


(a) shows a typical semicircular fracture mirror centered on an origin located at the specimen finished surface. Grinding created a semi elliptical surface crack that extends well below the striation depth. Depending upon the grain size and microstructure, the short semi elliptical cracks may be difficult to detect in polycrystalline ceramics since the cracks do not stand out clearly against the normal microstructure. An origin location on the surface is a necessary requirement but not sufficient proof that the origin is machining damage. In many instances, (particularly in beams in bending) natural material flaws may occur at the specimen surface.



(b) shows the same as above, except that an unusually deep machining striation is lined up with the machining crack. Deep striations may aid interpretation, but they may not necessarily be present since final finishing may eliminate any such traces.



(c) shows a machining crack that linked up with a natural material flaw such as an agglomerate or pore. The origin may be categorized either as an enlarged natural flaw or a hybrid natural flaw-machining damage. The natural flaw may make the material more susceptible to machining crack damage in the immediate vicinity of the flaw than elsewhere.



(d) shows the same as above, except that the natural flaw created a bump or jog in the fracture mirror. The irregularity at the origin created a step or curve in the fracture mirror that created a tail that extends well up into the mirror or even to its boundary.




FIG. X9.2 Fractographic Signs of Machining Damage or Scratches

TRANSVERSELY GROUND SURFACES


Common in biaxial disks and transversely-ground uniaxial flexural or tension strength specimens.

(a) **elongated “coplanar parallel crack”**
(or coplanar linked semi-elliptical cracks).

A deep striation may or may not necessarily be present. The fracture mirror may be **elongated** along the outer specimen surface.




(b) **elongated “coplanar parallel crack”** linked with a **natural flaw**. A step in the fracture origin emanates from the discontinuity.




(c) **“zipper crack”**

This is a series of short semi elliptical cracks, which have linked. A series of short tails, or **“machining crack hackle,”** emanate from the links or overlaps of the flaws and extend up into the fracture mirror. These tails may be tilted to the left or right and help confirm that fracture originated in the central region of the set. The short tails are telltale features of slightly misaligned or overlapping transverse machining cracks (or a scratch) and are often easier to see with an optical microscope with low angle lighting than with a scanning electron microscope. The fracture mirror may be elongated along the specimen outer surface or it may have one or two prominent **side lobes**. This origin type is common in transversely-ground rectangular flexure specimens or scratched biaxial disk specimens.




(d) **coarse “zipper crack”**

This is made up of a series of irregular, less coplanar semi-elliptical cracks. Larger tails than in (c) are created. In severe cases, the tail may extend all the way to the mirror boundary. The fracture mirror may be elongated. This origin is common in transversely ground or scratched specimens and the markings are sometimes termed **“shark’s teeth.”**



(e) **“V machining crack”**

The crack intersects the fracture surface at an angle. Only a portion of the machining crack or crack series is exposed. A pronounced step occurs in the fracture mirror. One or two (shown) tails extend well up into the fracture mirror. The machining direction is not quite perpendicular to the specimen length and uniaxial stress axis due to grinding wheel cross feed. This origin is common in cylindrical specimens prepared by centerless or cylindrical transverse grinding wherein the wheel and work piece displace axially relative to each other.



(f) **“coarse grinding parallel crack”**

The origin is a deep machining crack that extends along the entire surface. The origin is often bumpy since the origin is comprised of offset parallel cracks. Thin bands of uniform depth extend along the specimen surface on either side of the fracture mirror. The bands have the same depth as the grinding cracks. Short tails, or **“machining crack hackle”** which may be in the thin bands are tilted away from the origin. This origin type is common in coarse ground surfaces.




FIG. X9.3 Fractographic Signs of Machining Damage or Scratches

REFERENCES

- (1) Frechette, V. D., *Failure Analysis of Brittle Materials, Advances in Ceramics*, Vol 28, American Ceramic Society, Westerville, OH, 1990.
- (2) Swab, J. J. and Quinn, G. D., "Fractography of Advanced Structural Ceramics: Results From Topic #2 of the VAMAS Round Robin Exercise," *Ceramic Engineering and Science Proceedings*, Vol 16 [5], 1995, pp. 929–938.
- (3) Swab, J. and Quinn, G., "Results of a Round Robin Exercise on the Fractography of Advanced Structural Ceramics," *Ceramic Engineering and Science Proceedings*, Vol 15, [5], 1994, pp. 867–876.
- (4) Swab, J. J. and Quinn, G. D. "Fractography of Advanced Structural Ceramics, Results from the VAMAS Round Robin Exercise," *U.S. Army Technical Report, ARL-TR-656*, Dec. 1994; also published as *VAMAS Report #19*, National Institute of Standards and Technology, Gaithersburg, MD February 1995.
- (5) Quinn, G. D. and Swab, J. J., "Comparisons of Calculated and Measured Flaw Sizes," *Fractography of Glasses and Ceramics IV, Ceramic Transactions*, Vol 122 eds, J. Varner and G. Quinn, American Ceramic Society, Westerville, OH, 2001, pp. 175–192
- (6) Quinn, G. D. and Swab, J. J., "Fractography and Estimates of Fracture Origin Size from Fracture Mechanics," *Ceram. Eng. and Sci. Proc.*, 17 [3], 1996, pp. 51–58.
- (7) Johnson, J. W., and Holloway, "On the Shape and Size of the Fracture Zones on Glass Fracture Surfaces," *Phil. Mag.*, 14, 1996, pp. 731–743.
- (8) Kirchner, H. P., Gruver, R. M., and Sotter, W. A., "Fracture Stress-Mirror Size Relations for Polycrystalline Ceramics," *Philosophical Magazine*, Vol 33 [5], 1976, pp. 775–780.
- (9) Kirchner, H. P., Gruver, R. M., and Sotter, W. A., "Use of Fracture Mirrors to Interpret Impact Fracture in Brittle Materials," *Journal of the American Ceramic Society*, Vol 58 [5–6], 1975, pp. 188–191.
- (10) Kirchner, H. P., and Gruver, R. M., "Fracture Mirrors in Polycrystalline Ceramics and Glass," *Fracture Mechanics of Ceramics*, Vol 1, 1974, pp. 309–321.
- (11) Kirchner, H. P., and Gruver, R. M., "Fracture Mirrors in Alumina Ceramics," *Philosophical Magazine*, Vol 27 [6], 1976, pp. 1433–1446.
- (12) Congleton, J. and Petch, N. J., "Crack Branching," *Philosophical Magazine*, Vol 16 [142], 1967, pp. 749–760.
- (13) Bansal, G. K., and Duckworth, W. H., "Fracture Stress as Related to Origin and Fracture Mirror Sizes," *Journal of the American Ceramic Society*, Vol 60 [7–8], 1977, pp. 304–310.
- (14) Bansal, G. K., "On Fracture Mirror Formation in Glass and Polycrystalline Ceramics," *Philosophical Magazine*, Vol 35 [4], 1977, pp. 935–944.
- (15) Shetty, D. K., Rosenfeld, A. R., and Duckworth, W. H., "Crack Branching in Ceramic Disks Subjected to Biaxial Flexure," *Communications of the American Ceramic Society*, Jan. 1983, pp. C10–C13.
- (16) Duckworth, W. H., Shetty, D. L.K., and Rosenfeld, A. R., "Influence of Stress Gradients on the Relationship Between Fracture Stress and Mirror Size for Float Glass," *Glass Technology*, Vol 24 [5], 1983, pp. 263–273.
- (17) Mecholsky, Jr., J. J., Freiman, S. W., and Rice, R. W., "Fracture Surface Analysis of Ceramics," *Journal of Material Science*, Vol 11, 1976, pp. 1310–1319.
- (18) Mecholsky, J. J., Rice, R. W., and Freiman, S. W., "Prediction of Fracture Energy and Flaw Size in Glasses from Measurements of Mirror Size," *Journal of the American Ceramic Society*, 57 [10], 1974, pp. 440–443.
- (19) Marshall, D. B., Lawn, B. R., and Mecholsky, J. J., "Effect of Residual Contact Stresses on Mirror/Flaw Size Relations," *Journal of the American Ceramic Society*, Vol 63 [5-6], 1980, pp. 358–360.
- (20) Mecholsky, J. J. Jr., and Rice, R. W., "Fractographic Analysis of Biaxial Failure in Ceramics," *Fractography of Ceramics and Glass Failures, ASTM STP 827*, eds. J. Mecholsky and S. Powell, ASTM, Westerville, OH, 1984, pp. 185–193.
- (21) Mecholsky, J. J., Gonzalez, A. C., and Freiman, S. W., "Fractographic Analysis of Delayed Failure in Soda Lime Glass," *Journal of the American Ceramic Society*, 62 [11-12], 1979, pp. 577–580.
- (22) Quinn, G. D., Ives, L., Jahanmir, S., Koshy, P., "Fractographic Analysis of Machining Cracks in Silicon Nitride Rods and Bars," *Fractography of Glasses and Ceramics, IV, Ceramic Transactions*, Vol 122, eds., J. R. Varner and G. D. Quinn, American Ceramic Society, Westerville, OH 2001, pp. 343–365.
- (23) Quinn, G. D., Messier, D. R., Schioler, L. J., "Characterization of Ceramic Vane Materials for 10 kW Turboalternator," *U.S. Army Materials and Mechanics Research Center Technical Report TR 83-18*, April 1983.
- (24) Messier, D. R., Schioler, L. J., and Quinn, G. D., "Fracture Behavior and Strength of Reaction-Bonded Si₃N₄ Turbine Shrouds," *American Ceramic Society Bulletin*, Vol 60 [8], 1981, pp. 812–817.
- (25) Quinn, J. B., "Extrapolation of Fracture Mirror and Crack-Branch Sizes to Large Dimensions in Biaxial Strength Tests of Glass," *Journal of the American Ceramic Society*, Vol 82 [8], 1999, pp. 2126–2132.
- (26) Orr, L., "Practical Analysis of Fractures in Glass Windows," *Materials Research and Standards*, Vol 12 [1], 1972, pp. 21–23.
- (27) Kerper, M. J., and Scuderi, T. G., "Modulus of Rupture of Glass in Relation to Fracture Pattern," *American Ceramic Society Bulletin*, 43 [9] 1964, pp. 622–625.
- (28) Adams, P. B. and DeMartino, S. E., "Glass-Ceramic Cookware Failure Analysis," *Engineered Materials Handbook*, Vol 4, Ceramics and Glasses, ASM, Metals Park, OH, 1991, pp. 669–673.
- (29) Larsen, D. C. and Walther, G. C., "Property Screening and Evaluation of Ceramic Turbine Engine Materials," IIT Research Institute, Chicago IL, Interim Technical Report No. 5, IITRI D 6114-ITR-30, 1978.
- (30) Baker, L. K., and Glaesemann, G. S., "Branch Source Analysis, Alternate Mirror Measurement Method," *Proceedings of the International Wire and Cable Symposium*, Philadelphia, PA 1998, pp. 933–937.
- (31) Salem, J. A., Choi, S. R., and Powers, L. M., "Toughened Ceramics Life Prediction," *Ceramic Technology Project Semiannual Progress Report for October 1992 Through March 1993*, Oak Ridge National Laboratory Technical Report TM 12428, September 1993, pp. 307–316.
- (32) Choi, S., and Salem, J., "Indentation Flaw Formation and Strength Response of Silicon Nitride Ceramics at Low Indentation Loads," *Journal of Material Science Letters*, Vol 11, 1992, pp. 1398–1400.
- (33) Choi, S. R. and Gyekenyesi, J. P., "Crack Branching and Fracture Mirror Data of Glasses and Advanced Ceramics," *NASA Technical Report TM 1998-206536*, 1998.
- (34) Clark, A. B. J., and Irwin, G. R., "Crack Propagation Behaviors," *Experimental Mechanics*, Vol 6 [6], 1966, pp. 321–330.
- (35) Aoki, S., and Sakata, M., "Crack Bifurcation Under Hydrostatic Pressure," *Engineering Fracture Mechanics*, Vol 13 [3], 1980, pp. 491–499.
- (36) Woodtli, J., "Quantitative Fractographie in Keramik: Auswertung von Spiegelzonen in SiC," *Swiss Federal Laboratories for Materials Testing and Research, Report 157361*, Dec. 1997.
- (37) Chandan, H. C., and Parker, R. D., "Fractography of Optical Fibers," *Fractography of Glass*, eds. R. C. Bradt and R. E. Tressler, Plenum Press, NY 1994, pp. 143–184.

- (38) Abdel-Latif, A. I. A., Tressler, R. E., and Bradt, R. C., “Fracture Mirror Formation in Single Crystal Alumina,” *Fracture 1977*, ed. D. Taplin, University of Waterloo Press, 1977, pp. 933–939.
- (39) Reed, D. A. and Bradt, R. C., “Fracture Mirror-Failure Stress Relations in Weathered and Unweathered Window Glass Panels,” *Communications of the American Ceramic Society*, Nov. 1984, pp. C227–C229.
- (40) Ball, M. J., Landini, D. J., and Bradt, R. C., “Fracture Mist Region in a Soda-Lime Silica Float Glass,” in *Fractography of Ceramic and Metal Failures*, ASTM STP 827, Mecholsky, Jr., J., and Powell, S., eds., ASTM, 1984, pp. 110–120.
- (41) Bartolucci Luyckx, S., and Sannino, A., “Crack Branching and Fracture Mirrors in Cemented Tungsten Carbide,” *Journal of Material Science*, Vol 23, 1988, pp. 1243–1247.
- (42) Srinivasan, G. V., Gibson, J., and Lau, S. K., “The Origin of Strength Limiting Defects in a Toughened SiC (Hexoloy SX-SiC),” *Fractography of Glasses and Ceramics III, Ceramic Transactions*, Vol 64, eds, J. R. Varner, V. D. Frechette, and G. D. Quinn, American Ceramic Society, Westerville, OH, 1996, pp.181–192.
- (43) Morrell, R., Byrne, L., and Murray, M., “Fractography of Ceramic Femoral Heads,” *Fractography of Glasses and Ceramics, IV, Ceramic Transactions*, Vol 122, eds., J. R. Varner and G. D. Quinn, American Ceramic Society, Westerville, OH 2001, pp. 253–266.
- (44) Lewis, III, D., “Fracture Strength and Mirror Size in a Commercial Glass-Ceramic,” *Journal of the American Ceramic Society*, 64 [2], 1961, pp. 82–86.
- (45) Hulderman, F., Sanghera, J. S., and Mackenzie, J. D., “The Effect of UV Radiation on the Mechanical Strength of As₂Se₃ Glass Fibers,” *Journal of Non-Crystalline Solids*, Vol 127 1991, pp. 312–322.
- (46) Swab, J. J., LaSalvia, J. C., and Gooch, W. A., “Characterization of WC-Based Armor Ceramics,” to be published as a Technical Report by the Army Research Laboratory, Aberdeen Proving Ground, MD 21005.
- (47) J.R. Kelly, “Fractography of Dental Ceramics,” pp. 241–251 in *Fractography of Glasses and Ceramics, IV*, eds. J. Varner and G. Quinn, Ceramic Transactions Vol. 122, American Ceramic Society, Westerville, OH 43081, 2001.

SUMMARY OF CHANGES

Committee C28 has identified the location of selected changes to this standard since the last issue (C 1322 – 96) that may impact the use of this standard:

- (1) Appendix X7 was expanded with discrimination between inner and outer mirror constants and the inclusion of crack branching constants.
- (2) The select bibliography appendix (former Appendix X2) was shortened.
- (3) Eq 3 relating crack size to fracture energy was corrected.
- (4) More information about component failure analysis was added.
- (5) More illustrations of machining damage cracks and a new Appendix X9 on signs of machining damage were added.
- (6) The tables listing cleaning agents and storage media were dropped.
- (7) More references to digital image recording were added.
- (8) A new Appendix was added on interpreting cases wherein calculated origin sizes do not agree with measured origin sizes.
- (9) Addition of new terms relating to fractography and fracture origin types.
- (10) A simple flow chart for conducting a fractographic analysis was added.
- (11) Numerous updates and clarifications were made to Section 7, “Detailed Procedures and Characterization.”

ASTM International takes no position respecting the validity of any patent rights asserted in connection with any item mentioned in this standard. Users of this standard are expressly advised that determination of the validity of any such patent rights, and the risk of infringement of such rights, are entirely their own responsibility.

This standard is subject to revision at any time by the responsible technical committee and must be reviewed every five years and if not revised, either reapproved or withdrawn. Your comments are invited either for revision of this standard or for additional standards and should be addressed to ASTM International Headquarters. Your comments will receive careful consideration at a meeting of the responsible technical committee, which you may attend. If you feel that your comments have not received a fair hearing you should make your views known to the ASTM Committee on Standards, at the address shown below.

This standard is copyrighted by ASTM International, 100 Barr Harbor Drive, PO Box C700, West Conshohocken, PA 19428-2959, United States. Individual reprints (single or multiple copies) of this standard may be obtained by contacting ASTM at the above address or at 610-832-9585 (phone), 610-832-9555 (fax), or service@astm.org (e-mail); or through the ASTM website (www.astm.org).